Genova Plus Spectrophotometer



Operating Manual



Safety

Please read this information carefully prior to installing or using this equipment.

- **1.** The unit described in this manual is designed be operated only by trained personnel. Any adjustments, maintenance and repair must be carried out as defined in this manual, by a person qualified to be aware of the hazards involved.
- **2.** It is essential that both operating and service personnel employ a safe system of work, in addition to the detailed instructions specified in this manual.
- **3.** Other than for those items defined in the maintenance procedures herein there are no user serviceable items in this instrument. Removal of covers and attempted adjustment or service by unqualified personnel will invalidate the warranty and may incur additional charges for repair.
- **4.** References should always be made to the Health and Safety data supplied with any chemicals used. Generally accepted laboratory procedures for safe handling of chemicals should be employed.
- **5.** If it is suspected that safety protection has been impaired in any way, the unit must be made inoperative and secured against any intended operation. The fault condition should immediately be reported to the appropriate servicing authority.

Merci de lire attentivement ces informations avant d'installer ou d'utiliser cet appareil.

- **1.** L'appareil décrit dans ce manuel est conçu pour être utilisé uniquement par des personnes formées. Tout réglage, maintenance ou réparation doit être effectué comme décrit dans ce manuel, par une personne qualifiée consciente des risques encourus.
- **2.** Il est essentiel que les personnes utilisant et intervenant sur cet appareil respectent les règles de sécurité de travail, en plus des instructions détaillées précisées dans ce manuel.
- **3.** En-dehors des éléments décrits dans les procédures de maintenance ci-incluses, cet appareil ne contient aucun élément réparable par l'utilisateur. L'enlèvement des capots et les tentatives de réglage ou de réparation par des personnes non qualifiées invalide toute garantie et entraîne un risque de frais de réparation supplémentaires.
- **4.** Toujours se référer aux fiches techniques de santé et de sécurité accompagnant tout produit chimique utilisé. Respecter les procédures de laboratoire généralement acceptées pour la manipulation en toute sécurité des produits chimiques.
- **5.** Si l'utilisateur suspecte qu'un problème quelconque puisse mettre en cause la sécurité, l'appareil doit être rendu inopérant en empêchant son utilisation. Communiquer la défaillance constatée au service de maintenance compétent.

Bitte lesen Sie diese Hinweise vor Installation oder Gebrauch dieser Ausrüstung sorgfältig durch.

- **1.** Das in diesem Handbuch beschriebene Gerät darf nur von geschultem Personal bedient werden. Alle Anpassungen, Wartungsarbeiten und Reparaturen müssen entsprechend der Vorgaben in diesem Handbuch und von einer kompetenten Person, die mit den damit verbundenen Gefahren vertraut ist, durchgeführt werden.
- **2**. Es ist wichtig, dass sowohl das Bedienungs- als auch das Service-Personal zusätzlich zu den detaillierten Anweisungen in diesem Handbuch ein sicheres Arbeitssystem einsetzen.
- **3.** Mit Ausnahme der Teile, deren Wartungsverfahren in diesem Handbuch beschrieben sind, enthält dieses Gerät keine weiteren Teile, die vom Benutzer gewartet werden können. Das Entfernen von Abdeckungen und Versuche von hierfür unqualifiziertem Personal, Anpassungen oder Wartungsarbeiten durchzuführen, haben zur Folge, dass die Garantie verfällt und können zusätzliche Reparaturkosten auslösen.

- **4.** Es ist jederzeit auf die sicherheitsrelevanten Daten sämtlicher verwendeter Chemikalien Bezug zu nehmen. Allgemein anerkannte Labormethoden zum sicheren Umgang mit Chemikalien sollten eingesetzt werden.
- **5.** Besteht der Verdacht, dass die Sicherheitsvorrichtungen in irgendeiner Weise beschädigt wurden, muss das Gerät außer Betrieb genommen und gegen weiteren Gebrauch gesichert werden. Die Störung sollte der zuständigen Serviceeinrichtung unverzüglich gemeldet werden.

Leggere attentamente queste istruzioni prima di installare o utilizzare il dispositivo.

- **1.** L'unità descritta nel presente manuale è stata realizzata per essere utilizzata solo da personale che ha ricevuto l'apposita formazione. Qualsiasi operazione di regolazione, manutenzione e riparazione deve essere effettuata sulla base di quanto indicato nel presente manuale da personale qualificato consapevole dei rischi connessi.
- **2.** È fondamentale che il personale operativo e il personale addetto alla manutenzione utilizzino un sistema di lavoro sicuro, oltre a seguire le istruzioni specificate nel presente manuale.
- **3.** Oltre a quelli indicati nelle procedure di manutenzione, all'interno di questo dispositivo non sono presenti altri elementi sui quali è possibile effettuare interventi. La rimozione delle protezioni e qualsiasi tentativo di regolazione o di manutenzione posto in essere da personale non qualificato invaliderà la garanzia. In questi casi, sarà necessario pagare un importo per le riparazioni effettuate.
- **4.** È sempre necessario fare riferimento ai dati sulla salute e sulla sicurezza forniti con le sostanze chimiche utilizzate. Adottare le procedure di laboratorio generalmente accettate per la gestione delle sostanze chimiche.
- **5.** Nel caso in cui si sospetti che la salute possa essere pregiudicata in qualsiasi modo, disattivare l'unità per renderla inutilizzabile. Qualsiasi condizione di errore deve essere immediatamente segnalata al responsabile per la manutenzione.

Lea esta información atentamente antes de instalar o utilizar este equipo.

- **1.** La unidad descrita en este manual está diseñada para que solamente la utilice personal con formación. Cualquier operación de ajuste, mantenimiento y reparación debe llevarse a cabo del modo indicado en este manual y debe realizarla una persona cualificada que sea consciente de los peligros que implica.
- **2.** Es fundamental que tanto los operarios como el personal de servicio utilicen un sistema de trabajo seguro, así como las instrucciones detalladas que se especifican en este manual.
- **3.** Cualquier elemento que no se encuentre entre los definidos en los procedimientos de mantenimiento aquí descritos no podrá utilizarse en este instrumento. La extracción de las tapas y los intentos de ajuste o reparación por parte de personal no cualificado invalidarán la garantía y pueden incurrir en cargos adicionales por reparación.
- **4.** Siempre deberían consultarse los datos sobre Salud y Seguridad que se suministran con cualquier producto químico que se utilice. Es necesario llevar a cabo los procedimientos de laboratorio de aceptación generalizada para la manipulación segura de productos químicos.
- **5.** Si existe la sospecha de que las medidas protectoras de seguridad han quedado dañadas en cualquier modo, la unidad debe inutilizarse y protegerse contra toda operación que se intente llevar a cabo. El estado de fallo debe comunicarse inmediatamente a la autoridad de servicio de mantenimiento y reparación pertinente.

Contents

SAECTION 1 - Introduction 8 1.1 INSTRUMENT DESCRIPTION 8 1.2 INSTRUMENT SPECIFICATION 8 SECTION 2 - Installation 10 2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 REONT PANEL 13 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 Setting Security Codes 20 4.4.1 SECTION SECURITY AND SETTING PASSWORDS 20<			Page
1.1 INSTRUMENT DESCRIPTION 8 1.2 INSTRUMENT SPECIFICATION 8 SECTION ≥ - Installation 10 2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 SECURITY AND SETTING PASSWORDS 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.5 MODE SPELIFICION 21 4.6 GLP SETINGS 22 5.2 M	Safety		1
1.2 INSTRUMENT SPECIFICATION 10 2.1 UNPACKING 10 2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 5ECTION 3 - Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 5ECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 SECURITY AND SETTING PASSWORDS 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 <t< td=""><td>SECTION</td><td>I 1 - Introduction</td><td>8</td></t<>	SECTION	I 1 - Introduction	8
SECTION 2 - Installation 10 2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 3.6 FRONT PANEL 13 SECTION 3 - Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 SELUTION SECURITY COdes 20 4.4.1 SECURITY AND SETTINGS 22 4.5 MODE SELECTION 21 4.6 LIP SETTINGS 22	1.1	INSTRUMENT DESCRIPTION	
2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 SECTION 3 – Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 – Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Settings Sock 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 SECTION S – PHOTOMETER MENU OPTIONS 23 SECTION S – PHOTOMETER MENU OPTIONS<	1.2	INSTRUMENT SPECIFICATION	8
2.1 UNPACKING 10 2.2 INSTALLATION 10 2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 SECTION 3 – Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 – Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Settings Sock 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 SECTION S – PHOTOMETER MENU OPTIONS 23 SECTION S – PHOTOMETER MENU OPTIONS<	SECTION	I 2 – Installation	10
2.3 DISPLAY 11 2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 SECTION 3 – Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 – Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings lock 20 4.4.1 Settings lock 20 4.4.2 Settings lock 21 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GL P SETTINGS 22 5 MODE SELECTION 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2			
2.4 CONTROLS 12 2.5 REAR PANEL 13 2.6 FRONT PANEL 13 SECTION 3 - Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Setting Security Codes 20 4.4.2 Setting Security Codes 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 25 <	2.2	INSTALLATION	10
2.5 REAR PANEL 13 2.6 FRONT PANEL 13 SECTION 3 - Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.3 Method Lock 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 5.2 SECTION Security OPTIONS 23 5.2.1 MCA	2.3	DISPLAY	11
2.6 FRONT PANEL 13 SECTION 3 – Theory and Practice of Spectroscopy Measurements 14 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 15 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 – Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.3 Method Lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 5.7 SCREEN CONTRAST 22 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.2 METHOD SETUP 25 6.2.1 MODE SPECIFIC PARAMETERS <td>2.4</td> <td>CONTROLS</td> <td>12</td>	2.4	CONTROLS	12
SECTION 3 – Theory and Practice of Spectroscopy Measurements 1 4 3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 – Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 SECTION SECURITY COdes 20 4.4.2 SECURITY AND SETTING PASSWORDS 20 4.4.3 Method Lock 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings lock 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings lock 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings lock 20 4.5 MEDICE SELECTION 21 <td>2.5</td> <td>REAR PANEL</td> <td>13</td>	2.5	REAR PANEL	13
3.1 THEORY OF SPECTROSCOPY MEASUREMENT 14 3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 SECURITY AND SETTING PASSWORDS 20 4.4.3 Method Lock 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings Security Codes 20 4.4.3 Method Lock 20 4.4.1 SECURITY AND SETTING 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 SECTION 5 - PHOTOMETER MENU OPTIONS 23 5.2.1 SECTION 5 - PHOTOMETER MENU OPTIONS 23 5.2<	2.6	FRONT PANEL	13
3.2 NUCLEIC ACID DETERMINATION 14 3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.1 Settings Security Codes 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTION + ONDETER MENU OPTIONS 23 SECTION 5 - PHOTOMETER MENU OPTIONS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.2.1 Selecting a Wavelength 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.2.1 Selecting a Wavelength 25 6.2.2 <td>SECTION</td> <td>I 3 – Theory and Practice of Spectroscopy Measurements</td> <td>14</td>	SECTION	I 3 – Theory and Practice of Spectroscopy Measurements	14
3.3 SPECTROSCOPY MEASUREMENT 15 3.4 GOOD PRACTICE GUIDELINES 16 SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Setting Security Codes 20 4.4.2 Settings lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.1 Selecting a Wavelength 25 6.2.1 Selecting a Wavelength 26 6.2.2.2 Selecting a Wavelength 26 </td <td>3.1</td> <td>THEORY OF SPECTROSCOPY MEASUREMENT</td> <td>14</td>	3.1	THEORY OF SPECTROSCOPY MEASUREMENT	14
3.4. GOOD PRACTICE GUIDELINES 16 SECTION 4 − Instrument Setup 18 4.1. NAVIGATING AND SCREEN SETUP 18 4.2. TIME AND DATE 19 4.3. INSTRUMENT SETTINGS MENU 20 4.4. SECURITY AND SETTING PASSWORDS 20 4.4.1. Setting Security Codes 20 4.4.2. Settings lock 20 4.4.3. Method Lock 21 4.5. MODE SELECTION 21 4.6. GLP SETTINGS 22 4.7. SCREEN CONTRAST 22 SECTION 5 - PHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1. MODE SPECIFIC PARAMETERS 23 5.2. METHOD SET UP 23 5.2.1 Selecting a Wavelength 24 5.2 METHOD SETUP 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.1 Selecting Concentration Units 26 6.2.2.2 Usi	3.2	NUCLEIC ACID DETERMINATION	14
SECTION 4 - Instrument Setup 18 4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Setting Security Codes 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SECTION 5 - PHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2.1 Selecting a Wavelength 23 5.2.1 Selecting a Wavelength 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Using a Standard 27 6.2.2.3 <	3.3	SPECTROSCOPY MEASUREMENT	15
4.1 NAVIGATING AND SCREEN SETUP 18 4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Settings Security Codes 20 4.4.2 Settings lock 21 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SECTION 5 - PHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2.1 Selecting a Wavelength 23 5.2.1 Selecting a Wavelength 24 5.3 CALIBRATION 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Using a	3.4	GOOD PRACTICE GUIDELINES	16
4.2 TIME AND DATE 19 4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Settings Security Codes 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTION 5 - PHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETERS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Fact	SECTION	I 4 – Instrument Setup	18
4.3 INSTRUMENT SETTINGS MENU 20 4.4 SECURITY AND SETTING PASSWORDS 20 4.4.1 Setting Security Codes 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTOPHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Factor 27 6.3	4.1	NAVIGATING AND SCREEN SETUP	18
4.4.1 SECURITY AND SETTING PASSWORDS 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTION HOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2.1 Selecting a Wavelength 25 6.2.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2.1 Selecting Concentration Units 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6	4.2	TIME AND DATE	19
4.4.1 Setting Security Codes 20 4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 – PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.4 SAMPLE MEASURMENT 24 5.4 SAMPLE MEASURMENT 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28	4.3	INSTRUMENT SETTINGS MENU	20
4.4.2 Settings lock 20 4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 – PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 – Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28	4.4	SECURITY AND SETTING PASSWORDS	20
4.4.3 Method Lock 21 4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 – PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 – Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28	4.4.1	Setting Security Codes	20
4.5 MODE SELECTION 21 4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 – PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 – Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28		•	20
4.6 GLP SETTINGS 22 4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
4.7 SCREEN CONTRAST 22 SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 – PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 – Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
SPECTROPHOTOMETER MENU OPTIONS 23 SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3.1 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
SECTION 5 - PHOTOMETRICS 23 5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28	4.7	SCREEN CONTRAST	22
5.1 MODE SPECIFIC PARAMETERS 23 5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
5.2 METHOD SET UP 23 5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 – Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
5.2.1 Selecting a Wavelength 23 5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3. CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
5.3 CALIBRATION 24 5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
5.4 SAMPLE MEASURMENT 24 SECTION 6 - Concentration 25 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3.1 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
SECTION 6 - Concentration 6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.3.1 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
6.1 MODE SPECIFIC PARAMETERS 25 6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28	5.4	SAMPLE MEASURMENT	24
6.2 METHOD SETUP 25 6.2.1 Selecting a Wavelength 25 6.2.2 Settings 26 6.2.2.1 Selecting Concentration Units 26 6.2.2.2 Changing the Resolution 26 6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
6.2.1Selecting a Wavelength256.2.2Settings266.2.2.1Selecting Concentration Units266.2.2.2Changing the Resolution266.2.2.3Using a Standard276.2.2.4Using a Factor276.3CALIBRATION276.3.1Calibrating to a Standard28			
6.2.2Settings266.2.2.1Selecting Concentration Units266.2.2.2Changing the Resolution266.2.2.3Using a Standard276.2.2.4Using a Factor276.3CALIBRATION276.3.1Calibrating to a Standard28			
6.2.2.1Selecting Concentration Units266.2.2.2Changing the Resolution266.2.2.3Using a Standard276.2.2.4Using a Factor276.3CALIBRATION276.3.1Calibrating to a Standard28			
6.2.2.2Changing the Resolution266.2.2.3Using a Standard276.2.2.4Using a Factor276.3CALIBRATION276.3.1Calibrating to a Standard28			
6.2.2.3 Using a Standard 27 6.2.2.4 Using a Factor 27 6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
6.2.2.4Using a Factor276.3CALIBRATION276.3.1Calibrating to a Standard28			
6.3 CALIBRATION 27 6.3.1 Calibrating to a Standard 28			
6.3.1 Calibrating to a Standard 28		_	
3			

6.4	SAMPLE MEASUREMENT	28
6.4.1	Measuring a Sample After Calibrating to a Standard	28
6.4.2	Measuring a Sample After Calibrating to a Factor	29
SECTION	N 7 – Spectrum	30
7.1	MODE SPECIFIC PARAMETERS	30
7.1	METHOD SETUP	30
7.2.1	Scan Settings	31
7.2.1	Selecting Absorbance or % Transmittance	31
7.2.1.1	Setting Start and End Wavelengths	31
7.2.1.2	Setting the Scan Interval	32
7.2.1.3	Y-Axis Scaling	32
7.2.1.4	CALIBRATION	33
7.4	SAMPLE MEASUREMENT	33
7.5	DATA ANALYSIS	34
7.5.1	Peaks and Valleys Threshold	34
7.5.1	Peaks and Valleys Table	34
7.5.2	Spectral Points Analysis	35
7.5.5	Spectral Folitis Arialysis	22
SECTION	N 8 – Quantitation	37
8.1	MODE SPECIFIC PARAMETERS	37
8.2	METHOD SETUP	37
8.2.1	Quantitation Settings	38
8.2.1.1	Selecting Absorbance or % Transmittance	38
8.2.1.2	Selecting a Wavelength	38
8.2.1.3	Selecting Concentration Units	38
8.2.1.4	Changing the Resolution	38
8.2.1.5	Selecting the Number of Replicate Standard Measurements	39
8.2.1.6	Selecting Automatic or Manual Replicate Measurements	39
8.2.1.7	Selecting Number of Standards	39
8.2.2	Quantitation Table	39
8.2.2.1	Editing Standard Data	39
8.2.2.2	Creating a New Standard Curve	40
8.2.3	Standard Curve	41
8.3	CALIBRATION	42
8.4	SAMPLE MEASUREMENT	42
8.5	DATA ANALYSIS	43
SECTION	N 9 – Kinetics	44
9.1	MODE SPECIFIC PARAMETERS	44
9.2	METHOD SET UP	44
9.2.1	Kinetics Settings	45
9.2.1.1	Y-Axis Scaling	45
9.2.1.2	Setting Lag Time or Start on Level	46
9.2.1.3	Selecting Absorbance or % Transmittance	46
9.2.1.4	Changing the Resolution	46
9.2.1.5	Selecting Concentration Units	47
9.2.1.6	Using a Standard	47
9.2.1.7	Using a Factor	47
9.2.1.8	Selecting a Wavelength	48
9.2.1.9	Setting the Kinetics Measurement Time	48
9.3	CALIBRATION	48
9.4	SAMPLE MEASUREMENT	48
9.5	DATA ANALYSIS	49
		

SECTION	I 10 – MULTI-WAVELENGTH	51
10.1	MODE SPECIFIC PARAMETERS	51
10.2	METHOD SET UP	51
10.2.1	Multi-Wavelength Settings	52
10.2.1.1	Setting the Number of Wavelengths	52
10.2.1.2	Setting the Measurement Wavelengths	52
	Changing the Resolution	52
10.2.1.4	Selecting Concentration Units	52
	Setting the Concentration Calculation Equation and Factors	53
10.3	CALIBRATION	53
10.4	SAMPLE MEASUREMENT	53
LIEE CCII	ENCE MENU OPTIONS	54
	I 11 – Concentration Plus	54
11.1		54
	METHOD SETUP	54
	Selecting a Wavelength – Operating Menu	54
	Concentration Plus Settings	55
	Selecting a Wavelength – Concentration Plus Settings	55
	Selecting Concentration Units	55
	Changing the Resolution	56
	Using a Standard	56
	Using a Factor	56
	Setting the Dilution Factor	57
11.3		57 57
	Calibrating to a Standard	57 57
	Calibrating to a Standard Calibrating to a Factor	58
11.4	SAMPLE MEASUREMENT	58
11.4.1	Measuring a Sample After Calibrating to a Standard	58
11.4.2	Measuring a Sample After Calibrating to a Standard Measuring a Sample After Calibrating to a Factor	59
SECTION	I 12 – PURITY SCAN	60
SECTION	I 13 – MULTI-WAVELENGTH PLUS	61
13.1	MODE SPECIFIC PARAMETERS	61
13.2	METHOD SET UP	61
13.2.1	Multi-wavelength Plus Settings	62
13.2.1.1	Setting the Measurement Wavelengths	62
13.2.1.2	Changing the Resolution	62
13.2.1.3	Selecting Concentration Units	62
13.2.1.4	Setting the Dilution Factor	63
13.2.1.5	Setting the Reference Wavelength	63
13.2.1.6	Setting the Concentration Calculation Equation and Factors	63
13.3	CALIBRATION	64
13.4	SAMPLE MEASUREMENT	64
SECTION	I 14 – DNA	65
14.1	DNA MENU OPTIONS	65
14.2	dsDNA	65
14.3	ssDNA	65
14.4	RNA	66
14.5	OLIGONUCLEOTIDES	66
14.5	260 / 280	67
14.7	260 / 230	67
14.7	VARIABLE RATIO	67
14.8	CALIBRATION AND SAMPLE MEASUREMENT	68
14.フ	CALIDIATION AND SAMELE MEASUREMENT	ÖÖ

SECTION	I 15 – PROTEIN	69
15.1	PROTEIN MENU OPTIONS	69
15.2	PIERCE 660 ASSAY	69
15.3	BCA ASSAY	69
15.4	BRADFORD ASSAY	70
15.5	LOWRY ASSAY	70
15.6	BIURET ASSAY	71
15.7	DIRECT UV	71
15.8	CALIBRATION AND SAMPLE MEASUREMENT	71
SECTION	I 16 – OD 600	72
16.1	MODE SPECIFIC PARAMETERS	72
16.2	METHOD SETUP	72
16.2.1	Selecting a Wavelength	72
16.2.2	Settings	73
16.2.2.1	Using a Standard	73
16.2.2.2	Using a Factor	74
16.2.2.3	Using an Instrument Factor	74
	Setting the Dilution Factor	75
16.3	CALIBRATION	75
16.3.1	Calibrating to a Standard	76
16.3.2	Calibrating to a Factor	76
16.4	SAMPLE MEASUREMENT	76
16.4.1	Measuring a Sample After Calibrating to a Standard	76
16.4.2	Measuring a Sample After Calibrating to a Factor	77
SECTION	I 17 – SAVING, PRINTING AND AUTOLOGGING	78
17.1	SAVING METHODS	78
17.1.1	Saving Methods To Internal Memory	78
17.1.2	Saving Methods to USB Memory Stick	79
17.2	OPENING METHODS	80
17.2.1	Opening Methods From Internal Memory	80
17.2.2	Opening Methods From USB Memory Stick	80
17.3	DELETING METHODS	81
17.4	SAVING RESULTS	81
17.5	OPENING RESULTS	82
17.6	DELETING RESULTS	83
17.7	PRINTING	83
17.7.1	'	83
	Print Setup – PHOTOMETRICS, CONCENTRATION, MULTIWAVELENGTH AND OD 600	84
	Print Setup - SPECTRUM AND PURITY Print Setup - QUANTITATION AND PROTEINS	84
	Print Setup – QUANTIATION AND PROTEINS Print Setup – KINETICS	84 84
17.7.1.4	Printing Results	85
17.7.2	AUTOLOGGING	85
17.8.1	Setting the Number of Sample Repetitions	85
17.8.2	Selecting Result's Destination	87
17.0.2	LOCKED METHODS	87
17.10	CONNECTING TO A PC	87
18.1	I 18 – ACCESSORIES AND SPARE PARTS OPTIONAL ACCESSORIES	88 88
18.2	CONNECTING THE ACCESSORIES	88
18.2.1	Internal Printer	88
	Passive Accessories	89
	Active Accessories	80

18.2.3.1	Automatic 8 cell turret	90
18.2.3.2	Peltier	90
18.2.3.3	Sipper pump	91
18.2.3.4	Combined sipper Peltier pump	93
18.3	USING THE ACCESSORIES	93
18.3.1	Automatic 8 cell turret	93
18.3.1.1	Automatic 8 cell turret – supporting creation of a standard curve in quantitation	94
18.3.2	Peltier	94
18.3.3	Sipper pump	95
18.3.3.1	Manual Sipper Pump Settings	95
18.3.3.2	Timed Sipper Pump Settings	96
18.3.4	Combined sipper Peltier	98
18.4	SPARES	99
SECTION	19 – MAINTENANCE AND SERVICE	100
19.1	ROUTINE MAINTENANCE	100
19.2	LAMP REPLACEMENT	100
19.2.1	Xenon Lamp Module Replacement	100
19.3	FIRMWARE UPDATE PROCEDURE	100
19.4	SERVICE	100
SECTION	20 – TROUBLESHOOTING	101
20.1	ERROR CODES	101
20.2	TROUBLESHOOTING GUIDE	103
20.3	TECHNICAL SUPPORT	103
SECTION	21 – DECLARATION OF CONFORMITY	104
SECTION	22 – GLOSSARY OF ICONS	105

SECTION 1 - Introduction

1.1 INSTRUMENT DESCRIPTION

The Genova Plus is a UV/visible spectrophotometer dedicated to life science analysis. This spectrophotometer allows the measurement of DNA concentrations and purity ratios using wavelengths recorded at 260, 280 and 230nm, with an optional correction at 320nm. The Genova Plus is pre-programmed with Bradford, Lowry, Biuret, BCA and Direct UV methods for protein analysis. The Genova Plus has an OD measurement mode enabling users to measure optical density at 600nm for cell harvesting. The purity scan across the entire wavelength range from 198 to 1000nm displays any distorted peaks enabling impurities to be easily identified.

This life science spectrophotometer uses icon driven software and has an improved navigation system for easy and intuitive usability. As well as the dedicated life science measurement modes this instrument can also be used as a standard spectrophotometer with measurement modes for photometrics, concentration, multi-wavelength, spectrum scanning, quantitation and kinetics.

1.2 INSTRUMENT SPECIFICATION

INSTRUMENT SPECIFICATION	
	Genova Plus
Wavelength	
Range	198 to 1000nm
Resolution	1nm
Accuracy	± 2nm
Repeatability	± 0.5nm
Spectral bandwidth	5nm
Photometrics	
Transmittance	0 to 199.9%
Absorbance	-0.300 to 2.500A
Accuracy*	±1%T, ±0.01Abs at 1.000 Absorbance
Resolution	0.1%T, 0.001A
Stray light*	<0.5% at 340nm and 220nm
Concentration/Concentration Plus	
Range	0 to 9999
Resolution	Selectable 1/0.1/0.01/0.001
Calibration	Blank with a single standard or factor
Units	no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM,
	μM, nM, U, U/l, U/ml, g/l, mg/l, μg/l, ng/l, g/dl,
	mg/dl, µg/dl, mg/ml, µg/ml, ng/ml, µg/µl, ng/µl,
	mol/l, mmol/l,
Factor	0.001 to 10000
Standard	0.001 to 1000
Quantitation	
Range	0 to 9999
Resolution	Selectable 1/0.1/0.01/0.001
Calibration	Blank with up to 12 standards
Units	no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM,
	μM, nM, U, U/l, U/ml, g/l, mg/l, μg/l, ng/l, g/dl,
	mg/dl, μg/dl, mg/ml, μg/ml, ng/ml, μg/μl, ng/μl,
	mol/l, mmol/l

Curve fit algorithms Quadratic, quadratic through zero, linear, linear

through zero, interpolate

Multi-wavelength

Range 0 to 9999

Data points Up to 4 wavelengths

Calculations Sum, product, ratio, difference

Kinetics

Measurement Time 2 to 9999 seconds

Calibration Blank with a single standard or factor

Display Graphical and concentration

Analysis Concentration, rate of change, initial and final

absorbance/%T

Resolution Selectable 1/0.1/0.01/0.001

Spectrum/Purity Scan

Range 198 to 1000nm Scan interval Selectable 1, 2 or 5nm

Analysis Absorbance or % transmittance and peak and valley

wavelengths

Multi-wavelength Plus

Range 0 to 9999

Data points 3 wavelengths + optional reference wavelength

Calculations concentration, ratio

DNA

Measurement modes dsDNA, ssDNA, RNA, Oligonucleotides,

260/280, 260/230, Variable Ratio

Protein

Measurement modes Pierce 660, BCA, Bradford, Lowry, Biuret, Direct UV

OD 600

Range 0.00 E-19 to 9.99 E+19

Calibration Blank with a single standard or factor

Units cells/ml

Factor 0.01 E-19 to 9.99E+19
Standard 0.01 E-19 to 9.99E+19
Instrument Factor 0.001 to 9999.999

Other

Beam height 15mm Light source Xenon lamp

GLP Current time and date, user ID, settings lock and

method lock

Number of users 999

Methods memory 312 (including pre-programmed methods)
Results memory Limited by attached mass storage device

Removable media USB (supplied)

Outputs USB, Analogue, RS232, Internal printer

Power 24V

Size (w x d x h) 275 x 400 x 220mm

Weight 6kg

^{*}Assessment must be performed with a 630 204 - 10 x 10mm path length cuvette holder installed.

SECTION 2 – Installation

2.1 UNPACKING

Remove the Genova Plus from the packaging and ensure the following items are included:

- 1. Model Genova Plus spectrophotometer fitted with micro-cuvette holder (736 501)
- **2.** 24V 65W power supply unit (021 060)
- 3. Pack of 100 disposable UV micro-volume cuvettes 70µl (035 143)
- **4.** 4GB USB memory stick (019 146)
- 5. Instruction manual (736 505)
- **6.** Jenway Foreign Manual CD (JENMANCD)
- 7. 10x10mm single cuvette holder (630 204)

2.2 INSTALLATION

The Genova Plus is supplied ready to use.

The unit should be placed on a clean flat surface which is free from drafts and vibrations. The units are designed for operation on 90V to 264V AC input at 47 to 63Hz. Select the correct plug attachment and attach to the power supply unit as shown below:




Fig 2.2.1 - Power supply unit with various plugs

Connect the power supply unit to the power inlet socket on the rear panel of the instrument and connect to the mains socket. Turn the power on at the mains and switch the instrument on using the power switch on the rear of the instrument.

The instrument will initially check for firmware updates (Section 20.3) and then perform several poweron tests before displaying the main menu:





Fig 2.2.2 - All Power On Tests Complete

- **1.** Instrument check ensures the validity of the saved parameters
- 2. Dark test
- **3.** Checks for the accessory fitted. If an active accessory is found the instrument verifies communication and response
- **4.** Self calibration of wavelengths
- 5. Checks communication between USB memory stick port and the instrument

2.3 DISPLAY

The instrument has a dot matrix display which enables icons and graphs to be displayed clearly. Following successful completion of the power on tests the main menu screen will be displayed:



Life Science/Spectrophotometer menu options

- 1. Purity/Spectrum measurement mode
- 2. Concentration plus/Concentration measurement mode
- 3. Back key
- **4.** Time and date toggle and settings
- 5. Multi-wavelength plus/Multi-wavelength measurement mode
- 6. Toggle between Life Science and Spectrophotometer modes
- 7. Protein/Photometrics measurement mode
- 8. Instrument settings menu
- 9. DNA/Quantitation measurement mode
- 10. OD 600/Kinetics measurement mode

2.4 CONTROLS

The keypad used for this model enables an easy and effective way of navigating the different measurement modes, entering numbers, saving and analysing results. The soft keys are active when an icon is displayed above or adjacent to the key. The only exception to this is the back key which is always active.

The main Life Science menu screen and surrounding keypad is displayed below.




Fig. 2.4.1 - Display

Life Science/Spectrophotometer menu options

- 1. Purity/Spectrum measurement mode
- 2. Concentration plus/Concentration measurement mode
- 3. Back key
- **4.** Time and date toggle and settings
- 5. Multi-wavelength plus/Multi-wavelength measurement mode
- **6.** Toggle between Life Science and Spectrophotometer modes
- 7. Protein/Photometrics measurement mode
- 8. Instrument settings menu
- 9. DNA/Quantitation measurement mode
- 10. OD 600/Kinetics measurement mode

2.5 REAR PANEL

The image below shows the rear panel on the instrument:




Fig. 2.5.1 – Rear Panel

1. Lamp access panel Allows access to lamp when replacement is necessary

2. Power switch On/off switch for the unit

3. Power in socket Connection socket for power supply unit4. RS232 serial port Connection to a PC or external serial printer

5. Output sockets Analogue output

2.6 FRONT PANEL

The image below shows the front panel of the instrument:




Fig. 2.6.1 – Front Panel

- **1.** Integral printer (optional accessory)
- 2. Keypad
- 3. USB memory stick slot
- 4. Instrument lid
- 5. Display

SECTION 3 – Theory and Practice of Spectroscopy Measurements

3.1 THEORY OF SPECTROSCOPY MEASUREMENT

UV-visible spectroscopy is the measurement of the absorbance of light at a specific wavelength in a sample. This is used to identify the presence and concentration of molecular entities within the sample. The Beer-Lambert law is used to relate the absorption of light to the properties of the sample through which the light is travelling through. The Beer-Lambert law states that:

$$A = \varepsilon I c$$

A is the absorbance


is the molar absorption coefficient (I mol⁻¹cm⁻¹)

c is the concentration (mol I⁻¹)

I is the path length (cm)

This law shows that absorbance is linear to concentration but this is only true for low concentrations. For absorbance levels above 3 the concentration starts to move away from the linear relationship.

Transmittance is the proportion of the light which passes through the sample:



Where:

。 is the incident light

I, is the transmitted light

L is the path length

Therefore: $T = I_t$

Absorbance is inversely related to transmittance:

$$A = \frac{\log 1}{T}$$

3.2 NUCLEIC ACID DETERMINATION

DNA, RNA and oligonucleotides can be measured directly in aqueous solutions in a diluted or undiluted form. Aqueous buffers with low ion concentrations (e.g. TE buffer) are ideal for this method. The concentration is commonly determined by measuring at 260nm against a blank and then evaluating against a factor.

The Genova Plus has pre-defined methods installed which assume that absorption of 1 OD (A) is equivalent to approximately: 50µg/ml dsDNA, 37µg/ml ssDNA, 40µg/ml RNA and 30µg/ml for oligonucleotides.

DNA interference by contaminants can be assessed by the calculation of an absorption ratio. The ratios A260/A280 and A260/A230 are used to estimate the purity of nucleic acids, since proteins absorb at 280nm and substances such as peptides, phenols, aromatic compounds or carbohydrates absorb at 230nm. Pure DNA should have an A260/A280 ratio of approximately 1.8 and pure RNA 2.0. In pure nucleic acid samples the A260/A230 ratio should be approximately 2.2.

Nucleic acid concentration can also be estimated with the following calculations:

Conc (μ g/ml) = (Abs@260nm x 62.9) - (Abs@280nm x 36.0)

Conc (μ g/ml) = (Abs@260nm x 49.1) - (Abs@230nm x 3.48)

Referring to a blank value where no absorption should occur is commonly required. On the Genova Plus the default reference wavelength is 320nm and the user can include the measured absorbance value in all nucleic acid calculations. The default wavelength can be modified from 320nm if required.

3.3 SPECTROSCOPY MEASUREMENT

There are four main components of a spectrophotometer. These are a light source to emit a high and constant amount of energy over the full wavelength range; a method for separating the light into discreet wavelengths; a sample holder and a light detector.

The optical layout of the Genova Plus spectrophotometer is shown:




Figure 3.3.1 – Diagram of light path

The light from the pre-aligned xenon lamp is focused onto the grating, with 1200 lines per millimeter, which separates the light into discrete wavelengths. The diffracted spectrum of light then passes through a further slit and lens arrangement before passing through the sample in the sample chamber from left to right. The light which is not absorbed by the sample is transmitted through a collecting lens and onto the signal detector. The photo-diode detector used is mounted directly onto the detector PCB and the output is used to calculate the % transmittance. The result is displayed either as % transmittance or absorbance on the instrument display.

3.4 GOOD PRACTICE GUIDELINES

- **1.** For optimum performance all spectrophotometers should be sited in a clean, dry, dust free atmosphere. When in use ambient temperature and light levels should remain as constant as possible.
- **2.** If required adherence to Standard Operating Procedures (SOP) and Good Laboratory Practice (GLP) should be monitored with regular calibration checks and a suitable Quality Control (QC) programme.
- **3.** The sample chamber lid must be fully closed during measurement and before any readings are recorded or printed.
- **4.** The correct selection of sample containers is imperative for accurate and reproducible results:
- **a)** Check that the material of the sample container is compatible with the wavelengths to be used for measurement. In general glass can only be used down to 360nm or 320nm depending on quality. Standard plastic cuvettes can be used down to 320nm. Special UV versions can be used down to 260nm. Below this level quartz cuvettes must be used.
- b) Plastic disposable cuvettes should only be used ONCE.
- **c)** Glass cuvettes should be thoroughly cleaned after use. Discard when scratches become evident on optical surfaces.
- **d)** Care should be taken when selecting semi-micro or micro cuvettes. The cuvette window on the inner chamber (the area filled with sample) must be wider than the aperture in the sample holder or light will reach the detector without passing through the sample. In this case, semi-micro or micro cuvettes with self-screening black surrounds must be used or, alternative holders for these cuvettes should be used.
- **e)** Glass test tubes and other sample tubes should be used with care. Where possible, matched tubes should be used and any index mark set to the correct position before measurements are made.
- **f)** Ensure any sample containers used are compatible with the constituents of both the samples and standards they are to hold. Plastic cuvettes are not compatible with organic solvents.
- **g)** All sample containers must be handled with care; by the top, bottom and non-optical surfaces only. Any finger marks evident must be removed by a suitable cleaning process.
- **h)** Flow-through cuvettes must be selected with care and consideration for the sample type, sample volume, pumping system, rinse, sample and waste handling to be used.
- **5.** Samples and standards should not be stored in open cuvettes or sample containers as evaporation will change the value and lead to staining of the walls which may be irreversible. If stored in stoppered and sealed cuvettes, they should be filled with little or no air space and the values regularly checked against a reference standard or quality control material.
- **6.** Samples should be allowed to equilibrate to ambient temperature before measurement (unless a suitable temperature controlled sample holder is in use). Temperature change during measurement may cause air bubbles to form on the walls of the sample holder. This is a common cause of drift during measurement.
- **7.** In the preparation of samples and standards high grade borosilicate glass and AR grade chemicals and reagents must be used. Good quality deionised water or other suitable solvents must be used for dissolving or diluting samples, chemicals and reagents.
- **8.** All measurements require calibration to a blank, for maximum accuracy this should be prepared with care using the same deionised water or solvent used for dissolving or diluting the sample. Where reagents are added to the sample to produce a colour proportional to its concentration a 'sample based' blank should be used. In this case the blank should consist of all reagents or chemicals to be used, **except** the sample which will produce the colour to be measured.

- **9.** Deviations from the Beer-Lambert Law may occur at high and low concentrations giving non-linear response during sample concentration measurements. For all new methods a linear range should be defined by the preparation of a calibration curve. The quantitation mode may be used to construct such a curve against which sample results are automatically measured.
- **10.** Cuvettes and sample holders must be filled to a minimum level which covers the light path. All Jenway spectrophotometers have a beam height of 15mm.
- **11.** The instrument must be calibrated to zero absorbance/100% transmittance prior to taking readings. In the spectrum measurement mode a baseline scan must be performed before performing a sample scan.

SECTION 4 – Instrument Setup

4.1 NAVIGATING AND SCREEN SETUP

The main life science menu screen is displayed below.




Fig 4.1.1 – Life Science Home Screen





Fig 4.1.2 – Spectrophotometer Home Screen

To navigate around the spectrophotometer screen press the soft keys adjacent to icons displayed on the screen. There is a back key which returns to the previous menu without saving any changes.

The main menu screens provide access to all measurement modes, the time and date menu and the instrument settings menu. The measurement modes are specific to each of the instrument's two home screens. The life science home screen gives access to the purity scan, concentration plus, multi-wavelength plus, protein, DNA and OD 600 modes, whereas the spectrophotometer home screen gives access to the spectrum, photometrics, quantitation, concentration, multi-wavelength and kinetics modes. The instrument settings menu enables access to settings lock, security codes, method lock, mode selection, user ID and screen contrast menus.




Operating Menu (Photometrics measurement mode)


When a measurement mode is opened the operating menu enables changes to measurement parameters and settings to be made. Depending on the mode, the measurement parameters can be accessed through the settings menu which is displayed in the top right hand corner of the screen. The only mode where this function is not available is the photometrics mode; instead a toggle icon is displayed which is used to change the primary and secondary displays. The DNA and protein modes require the user to initially select a method before the operating menu option is available.

The utility toolbar is displayed on the left hand side of the operating menu and provides the same functions in all of the measurement modes. This toolbar enables access to printing, print setup options, opening, saving and deleting results and methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.


4.2 TIME AND DATE



The time and date menu enables the current time and date to be set. This information will be saved on all results and displayed on printouts. The time and date menu can be accessed from the main menu by holding the key below the time and date icon for 2 seconds. Pressing the key once cycles the display between time and date.



In the time and date menu to set the time press the key adjacent to the clock icon. Select the digit to be changed using the keys at the bottom of the screen. Use the keys adjacent to the arrow icons to increase or decrease the number. The clock function uses a 24 hour format.



In the time and date menu to set the date press the key adjacent to the calendar icon. Select the digit to be changed using the keys at the bottom of the screen. Use the keys adjacent to the arrow icons to increase or decrease the number. The date format can be displayed as either European dd/mm/yy or American mm/dd/yy.

To change between the two formats press the key below the toggle icon. Once the current time and date have been set press the key adjacent to the tick icon to save the changes. To exit this menu without saving any changes press the back key and the screen will return to the main menu.

4.3 INSTRUMENT SETTINGS MENU

The instrument settings menu is accessed by pressing the key below the instrument settings icon in the main menu. This menu enables access to settings lock, security code, method lock, mode selection, user ID and screen contrast menus. The tick icon saves any changes made and returns to the main menu.





Fig 4.3.1 - Settings Menu

4.4 SECURITY AND SETTING PASSWORDS

4.4.1 Setting Security Codes




The security code function enables a security code to be set to lock the instrument settings and measurement mode settings. The security code is not specific to the user ID but is designed to enable an administrator to control either the instrument or protocols. The security code menu is accessed through the instrument settings menu.



In the instrument settings menu press the key adjacent to the security code icon. Using the keys at the bottom of the screen select the digit to be changed. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Once the preferred code has been set press the key adjacent to the tick icon to save the security code.


4.4.2 Settings lock

The settings lock function enables the instrument and measurement mode settings to be locked to prevent any changes to the measurement parameters or instrument settings. The only exceptions to this are that the user ID and contrast can be changed when the settings lock is active.



The settings lock function is accessed through the instrument settings menu by pressing the key adjacent to the open padlock icon. One press will lock the settings instantly. To unlock the settings press the key again. This will open the security code menu as detailed in section 4.4.1. The previously set security code must be entered to unlock the settings. When the settings lock is active

methods can still be opened, deleted and saved but the method parameters cannot be changed.



To enter the security code, use the keys at the bottom of the screen to select the digit to be changed. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Once the correct security code has been entered press the key adjacent to the tick icon. The settings are now unlocked.

If the settings are locked before the security code has been set a default code of 660 will unlock the settings.

4.4.3 Method Lock





When the method lock is active the method selection menu is disabled in all the measurement modes therefore methods cannot be opened, deleted or saved. However the measurement parameters of the currently loaded method can be changed. The method lock function is accessed through the instrument settings menu by pressing the key adjacent to the method lock icon. One press will lock the methods instantly. To unlock the methods press the


key adjacent to the method lock icon again. The methods are now unlocked. If the settings lock is active this must be disabled before the method lock can be activated or deactivated.

In all the measurement modes if a user tries to save changes to a method when the method lock is active the padlock icon flashes on the screen and changes cannot be saved.

4.5 MODE SELECTION








The mode selection function enables access to the various measurement modes to be restricted. The required modes can be selected and the settings lock activated to prevent other users from accessing the deactivated modes. The mode selection function can be accessed through the instrument settings menu by pressing the key adjacent to the mode selection icon. The measurement mode icons which are displayed on the main menu are identified with a mode shown icon. The mode icons which are not displayed on the main menu are identified with a mode not shown icon. To change a mode from displayed to restricted or vice versa press the key adjacent to the measurement mode icon. Once the required modes have been selected press the key adjacent to the tick icon to save the changes. The selected measurement modes will be displayed on the main menu.

The same procedure can be used to restrict the mode access in the spectrophotometer home screen.


4.6 GLP SETTINGS

In addition to the time and date settings this instrument also has a user ID function. This function enables an individual three digit ID number to be set. This will be displayed on all printouts and saved results.



The user ID function can be accessed through the instrument settings menu by pressing the key adjacent to the user ID icon. Use the keys at the bottom of the screen to select the digit to be changed. Use the keys adjacent to the arrow icons to increase or decrease the number. Once the preferred user ID has been set press the key adjacent to the tick icon to save and return to the instrument settings menu.

4.7 SCREEN CONTRAST




The screen contrast function enables the brightness of the screen to be set. In the instrument settings menu press the key adjacent to the screen contrast icon. Use the keys below the arrow icons to increase or decrease the screen contrast. Once the required contrast level has been reached press the key adjacent to the tick icon to save and return to the instrument settings menu.

SPECTROPHOTOMETER MENU OPTIONS SECTION 5 – Photometrics

The photometrics measurement mode enables simple measurements of absorbance and % transmittance to be performed. The sample is measured at one wavelength and at one point in time. There are no post measurement calculations available in this measurement mode.

5.1 MODE SPECIFIC PARAMETERS



The photometrics operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.





Fig 5.1.1 - Operating Menu

5.2 METHOD SET UP



This measurement mode is very simple and the only parameters which can be adjusted are the wavelength and the display format.


The toggle icon enables the large primary display to be set to show the absorbance or % transmittance.

To change the primary and secondary displays press the key adjacent to the toggle icon. Repeat presses will cycle the display between absorbance and % transmittance.

5.2.1 Selecting a Wavelength

The wavelength can be adjusted by using the keys adjacent to the arrow icons to increase or decrease the wavelength. Once the required wavelength has been selected a calibration can be performed.


5.3 CALIBRATION



The calibration must be performed at the same wavelength at which the sample will be measured. Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. This sets the instrument to zero absorbance and 100% transmittance.

Once the calibration is complete the measure sample icon appears and the sample can be measured. If the wavelength is adjusted before a sample is measured the measure sample icon will disappear and the instrument must be calibrated again at the new wavelength.

5.4 SAMPLE MEASURMENT




It is not possible to measure a sample before the instrument has been calibrated at the selected wavelength. Once the calibration has been performed the measure sample icon is displayed and a sample can be measured. Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample holder. Close the instrument lid and press the key below the measure sample icon. Once the measurement is complete the photometric result will be shown on the screen.

Subsequent samples can be measured in the same way. If the wavelength is adjusted between sample measurements then the instrument must be calibrated again before more samples can be measured.

SECTION 6 – Concentration

The concentration measurement mode enables simple measurements of absorbance and concentration to be performed. In this measurement mode it is possible to calibrate against a standard of a known concentration or use a known factor. The sample is measured at one wavelength at one point in time. There are no post measurement calculations available in this measurement mode.

6.1 MODE SPECIFIC PARAMETERS



The concentration operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17. The settings icon enables the wavelength, units, resolution, standard or factor to be set.






Fig 6.1.1 - Operating Menu

6.2 METHOD SETUP


6.2.1 Selecting a Wavelength



The wavelength can be adjusted in the operating menu or in the settings menu. To adjust the wavelength, in the operating menu, use the keys adjacent to the arrow icons to increase or decrease the wavelength.



The settings menu is accessed through the operating menu by pressing the key adjacent to the settings icon. In the settings menu press the key below the wavelength icon.



This will open a number entry screen. Use the keys at the bottom of the screen to select the digit to be adjusted. Use the keys adjacent to the arrow icons to increase or decrease the wavelength to the required number. Press the key adjacent to the tick icon to save the changes and return to the settings menu.

6.2.2 Settings

The settings menu enables the wavelength, units, resolution, standard or factor to be set and is accessed from the operating menu by pressing the key adjacent to the settings icon. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.





Fig 6.2.2.1 - Settings Menu

When setting the method parameters either the standard or the factor should be selected. The standard should be used if the factor is not known as selecting this option will calculate the factor. If the factor is known it is not necessary to measure a known standard's concentration. When the standard or factor is not selected the value should be set to 1.00.

6.2.2.1 Selecting Concentration Units

The units of concentration can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μ M, nM, U, U/l, U/ml, g/l, mg/l, μ g/l, ng/l, μ g/l, mg/dl, μ g/dl, mg/ml, μ g/ml, ng/ml, μ g/ μ l, ng/ μ l, mol/l, mmol/l.




In the settings menu, press the key below the units icon. This opens the unit selection screen which displays all the different units. Use the keys adjacent to the arrow icons to navigate around the screen to select the required units. Once the required units have been highlighted press the key adjacent to the tick icon to save and return to the settings menu. The selected unit will be displayed in the operating menu along with absorbance and selected wavelength.

6.2.2.2 Changing the Resolution

The resolution that the concentration is displayed as can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon in the settings menu.

6.2.2.3 Using a Standard




The standard menu enables the value of a standard to be entered. This function is accessed by pressing the key adjacent to the standard icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.

For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Standard values from 0.001 to 1000 can be entered. The standard value can be reset to one by pressing the key adjacent to the 001 icon. Once the standard value has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the standard icon.

A standard value should only be entered if the factor is not known. If the factor is known the standard value should be set to 1.000.

6.2.2.4 Using a Factor




The factor menu enables a factor to be entered. This function is accessed by pressing the key adjacent to the factor icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.

For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Factor values of 0.001 to 10,000 can be entered. The factor value can be reset to one by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the factor icon.

If the factor is not known a standard should be measured in order to calculate the factor. If a standard is used the factor value should be set to 1.000.

6.3 CALIBRATION




In the concentration measurement mode calibrations against a standard or a factor can be performed following a zero calibration. If the factor is not known calibration against a known standard is performed in order to calculate the factor. However if the factor is known there is no need to calibrate using a standard.

The calibration must be performed at the same wavelength at which the sample will be measured.


6.3.1 Calibrating to a Standard

Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Insert a cuvette containing the standard concentration sample solution into the sample chamber and close the instrument lid.




Press the key below the calibrate to zero absorbance or standard icon, this will open another menu with the option to re-calibrate to zero absorbance or to calibrate to the previously entered standard value. Press the key adjacent to the calibrate to standard icon.

If the standard selected requires a factor beyond the range of the instrument the check standard icon will be displayed.



The instrument will take a reading and calibrate to the standard concentration. Once the calibration is complete the sample can be measured using the measure to standard icon.

6.3.2 Calibrating to a Factor




Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Once the calibration is complete the sample can be measured using the measure to factor icon.

6.4 SAMPLE MEASUREMENT


It is not possible to perform sample measurements before the instrument has been calibrated at the selected wavelength. In this operating mode the type of sample measurement performed depends on the calibration which has been carried out.

6.4.1 Measuring a Sample After Calibrating to a Standard



Remove the cuvette containing the standard sample and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to standard icon. Once the measurement is complete the concentration and absorbance values are displayed.

6.4.2 Measuring a Sample After Calibrating to a Factor




Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to factor icon. Once the measurement is complete the concentration and absorbance values are displayed.

In order to measure a sample based on a known factor the value for the factor must be entered in the settings menu before commencing measurement of the sample.

SECTION 7 – Spectrum

The spectrum measurement mode enables measurements of absorbance or % transmittance over a range of wavelengths to be performed. The absorbance or % transmittance at each wavelength is plotted graphically. Post measurement tools such as peaks and valleys analysis and spectral points analysis can be performed. This operating mode can be used to partially characterise a sample.

7.1 MODE SPECIFIC PARAMETERS



The spectrum operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.

The scan settings icon enables the graph y-axis, absorbance or % transmittance operating mode, start and end wavelengths and scan interval to be set. The peaks and valleys threshold icon enables the peaks and valleys threshold to be set. The peaks and valleys table icon enables the peaks and valleys of the scan to be viewed in tabular form. The spectral points analysis icon enables points to be selected from the scan for post measurement analysis.





Fig 7.1.1 - Operating Menu – Post Measurement

7.2 METHOD SETUP



In this measurement mode all of the method setup parameters are accessed through the scan settings menu. To open the scan settings menu press the key adjacent to the scan settings icon in the operating menu.

7.2.1 Scan Settings

This function enables the graph y-axis, absorbance or % transmittance operating mode, start and end wavelengths and scan interval to be set. To access this function press the key adjacent to the scan settings icon in the operating menu.





Fig 7.2.1.1 - Scan Settings Menu

7.2.1.1 Selecting Absorbance or % Transmittance


The operating mode is displayed on the left hand side of the menu. The default parameter is absorbance and pressing the key adjacent to the ABS icon cycles the operating mode between absorbance and % transmittance.

7.2.1.2 Setting Start and End Wavelengths

This function enables the start and end wavelengths of the spectrum scan to be set. The Genova Plus has a spectrum range from 198 to 1000nm. To set the start wavelength in the scan settings menu press the key adjacent to the wavelength on the far left of the x-axis. This opens the number entry screen.



Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. Once the required start wavelength has been entered press the key adjacent to the tick icon to save and return to the scan settings menu.



To set the end wavelength in the scan settings menu press the key adjacent to the wavelength icon on the far right of the x-axis. This opens the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the arrow keys to increase or decrease the number. Once the required end wavelength has been entered press the key adjacent to the tick icon to save and return to the scan settings menu.

If the start wavelength entered is the same as the end wavelength the end wavelength will automatically be set to be one times the scan interval. For example, if the start wavelength is entered as 500nm but the end wavelength is already set to 500nm and the scan interval is 2nm, the end wavelength will be automatically adjusted to 502nm. If the end wavelength entered is the same as the start wavelength


the start wavelength will automatically be set to be one times the scan interval. For example, if the end wavelength is entered as 500nm but the start wavelength is already set to 500nm and the scan interval is 2nm, the start wavelength will be automatically adjusted to 498nm.

7.2.1.3 Setting the Scan Interval


This function enables the interval between wavelengths measured in the spectrum scan to be set. The scan interval can be altered to 1, 2 or 5nm by pressing the key below the scan interval icon. Repeat pressing of the key cycles the interval between 1, 2 or 5nm. The scan interval can only be selected if the wavelength range is divisible by this number. For example a scan interval of 5nm cannot be selected for a wavelength range of 400 to 503nm.

7.2.1.4 Y-Axis Scaling


This function enables the scale of the y-axis of the spectrum graph to be adjusted either manually or automatically. The automatic scaling is represented by the hand icon with a cross through it and the manual scaling by the hand icon without the cross. To select manual or automatic scaling press the key adjacent to the hand icon. Repeat pressing of the key cycles between manual and automatic scaling.




In automatic y-axis scaling the absorbance or % transmittance values are cleared from the settings screen. When the spectrum scan has been completed the y-axis is automatically re-scaled.



In manual scaling the minimum and maximum absorbance or % transmittance values can be set. To change the absorbance or % transmittance values press the key adjacent to the minimum y-axis value, this opens a number entry screen.




Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. To change the sign press the key below the + or - icon. Repeat presses will cycle between + and –. Once the required absorbance or % transmittance value has been entered press the key adjacent to the tick icon.




To change the maximum absorbance or % transmittance value press the key adjacent to the maximum y-axis value, this opens a number entry screen. Use the keys adjacent to the arrow icons to increase or decrease the number. To change the sign press the key below the + or - icon. Repeat presses will cycle between + and -. Once the required absorbance or % transmittance value has been entered press the key adjacent to the tick icon.


7.3 CALIBRATION



In the spectrum measurement mode the calibration is a baseline scan which is performed across the selected wavelength range at the selected scan interval. Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the baseline scan icon to initiate the baseline scan. The baseline icon will change to show baseline scan in progress icon and a progress bar will be displayed.




To stop the baseline scan before completion press the key below the baseline scan in progress icon. Confirmation will be needed to stop the baseline scan. Press the key adjacent to the tick icon to confirm stopping the baseline scan and return to the operating menu.



Press the key adjacent to the cross icon to continue the baseline scan. Once the baseline scan has been completed the scan sample icon is displayed and a sample can be measured.


If the wavelength range, or the scan interval, is changed before a sample scan is performed a new baseline scan must be performed across the new wavelength range, at the new scan interval, before a sample can be measured.

7.4 SAMPLE MEASUREMENT




It is not possible to measure a sample before a baseline scan has been performed. Insert a cuvette containing the sample to be measured in the sample chamber and close the instrument lid. Press the key below the scan sample icon to start the spectrum scan of the sample.

The instrument will perform a scan across the wavelength range and scan interval previously selected. The scan sample icon will change to show the spectrum scan is in progress icon.




To stop the scan before completion, press the key below the scan in progress icon. Confirmation will be needed to stop the sample scan. Press the key adjacent to the cross icon to continue with the scan of the sample or press the key adjacent to the tick icon to confirm stopping the scan. Depending on how many data points have been measured either a partial scan and all the post measurement tools will be displayed, or the instrument will return to the operating menu with no measurements saved.



Once the scan is completed the spectrum will be shown on the screen. If automatic scaling was selected the y-axis will automatically be re-scaled.


7.5 DATA ANALYSIS




The post measurement tools icons are displayed on the screen following the completion of the scan. The tools include peaks and valleys threshold, peaks and valleys table and spectral points analysis. The peaks and valleys table displays all the detected peaks and valleys above the selected threshold value.

The spectral points analysis function enables points to be selected from the scan to analyse absorbance or % transmittance at selected wavelengths.

7.5.1 Peaks and Valleys Threshold




This function enables the peaks and valleys threshold to be set at 1, 5, 10% or turned off. To select the threshold value press the key adjacent to the peaks and valleys threshold icon. Repeat presses of the key will cycle through 1%, 5%, 10% and off.




The threshold is calculated as:


If the peaks and valleys are turned off this is represented by the peaks and valleys icon with a cross in place of a number. When the peaks and valleys threshold is switched off the peaks and valleys table icon is not displayed. If a 5% threshold is selected then only peaks and valleys above this threshold will be displayed in the peaks and valleys table.




7.5.2 Peaks and Valleys Table



This function displays all the detected peaks and valleys above the selected threshold, in tabular form. To open the table press the key adjacent to the peaks and valleys table icon. If the peaks and valleys threshold is switched off this icon is not displayed.



In the peaks and valleys table screen it is possible to display both peaks and valleys, just peaks or just valleys. To display the peaks only press the key below the peak only icon. To redisplay the peaks and valleys press the same key again.




To display the valleys only press the key below the valley only icon. To redisplay the peaks and valley press the same key again.

In the table the absorbance or % transmittance values (depending on the operating mode selected in the scan settings) are shown with the corresponding wavelength. Use the keys adjacent to the arrow icons to scroll up or down through the readings in the table. Press the key adjacent to the tick icon to return to the operating menu.


7.5.3 Spectral Points Analysis

The spectral points analysis function enables points to be selected from the scan to analyse the absorbance or % transmittance at a selected wavelength. To access this function press the key adjacent to the spectral points analysis icon and this opens the selection screen.




A solid vertical line will appear on the far right of the screen. Use the keys below the greater than (>) or less than (<) icons to move the line along the spectrum by decreasing or increasing the wavelength by one scan interval, the double greater than (>>) or less than (<<) icons increase or decrease the wavelength by ten times the scan interval.

As the vertical line moves along the scan the wavelength and absorbance or % transmittance value is displayed at the top of the screen. To add the selected point from the spectrum to the spectral points analysis table press the key adjacent to the add points to spectral points analysis table icon.




Only 6 points can be stored in the spectral points analysis table. When adding a selected point to the table the position this point is in the table will flash up on the screen. If the table is full and a 7th point is selected to go into the table a warning symbol will flash up and a point must be deleted from the table before another point can be added.



The wavelength to be analysed can also be entered manually. This can be done in two ways; firstly by pressing the key below the wavelength icon in the spectral points analysis menu. This opens a number entry screen where the wavelength can be input manually. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase

or decrease the number. Once the wavelength has been entered press the key adjacent to the tick icon to save and return to the spectral points analysis menu.



Secondly, the wavelength can also be entered manually in the spectral points analysis table by pressing the key adjacent to the location in the table where the result is to be stored. This opens a number entry screen where the analysis point can also be deleted by pressing the key adjacent to the delete icon.

Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. Once the required wavelength has been entered or the analysis point deleted press the key adjacent to the tick icon to save and return to the spectral points analysis table. If a wavelength entered is outside the scan range the check number warning icon will be displayed before the wavelength is automatically adjusted to within the range.

λ(nm)	****	ABS	_/
444	1	0.873	
446	2	0.873	
448	3	0.833	
	иT		

λ(nm)	1	ABS	/	
450	4	0.756		
452	5	0.678		
454	6	0.621		
T ×T				


To view the points in the spectral points analysis table press the key adjacent to the spectral points analysis table icon. Only three points can be displayed on the screen at one time; to view the other points in the table press the key below the down arrow icon. To view the first three points again press the key below the up arrow icon. The table displays the wavelength and either the corresponding absorbance or % transmittance, as well as the order in which the points were selected or entered. To change the photometric value between absorbance and % transmittance press the key below the ABS icon or %T icon. Pressing the key adjacent to the tick icon will save any changes made and return to the spectral points analysis menu.

It is possible to access spectral points analysis before a scan is performed. Points to be analysed can be pre-selected from the blank axis, or entered manually in the spectral points analysis table. When the scan has been performed the points for analysis will already be in the table with the corresponding absorbance or % transmittance values.

SECTION 8 – Quantitation

The quantitation measurement mode enables sample concentrations to be calculated using a standard curve. In this mode a number of standard solutions covering a range of known concentrations are measured at a set wavelength. The absorbance or % transmittance of these solutions is plotted to create a standard curve with replicate standards measurements, if required. Once the standard curve has been created a sample of unknown concentration can be measured and the concentration calculated using the standard curve.

8.1 MODE SPECIFIC PARAMETERS



The quantitation operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.

Operating Menu

The quantitation settings menu enables the absorbance or % transmittance operating mode, wavelength, units, resolution, number of replicate measurements (manual or automatic) and number of calibration standards to be set. The quantitation table menu enables the quantitation standard data to be viewed, edited and allows a new curve to be created. The standard curve menu enables a standard curve to be created, viewed and edited.





Fig 8.1.1 - Operating Menu – Post Calibration

8.2 METHOD SETUP



In this measurement mode the method setup parameters are accessed through the quantitation settings menu. To open the quantitation settings menu press the key adjacent to the quantitation settings icon in the operating menu.

8.2.1 Quantitation Settings

This function enables the absorbance or % transmittance operating mode, wavelength, units, resolution, number of replicate measurements (manual or automatic) and number of calibration standards to be set. To access this function press the key adjacent to the quantitation settings icon in the operating menu.





Fig 8.2.1.1 - Quantitation Settings Menu

8.2.1.1 Selecting Absorbance or % Transmittance

The operating mode can be changed between absorbance and % transmittance by pressing the key below the Abs or %T icon. Repeat presses will cycle between absorbance and % transmittance.

8.2.1.2 Selecting a Wavelength




To adjust the wavelength, press the key adjacent to the wavelength icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed, pressing the key twice to select the second digit. The keys adjacent to the arrow icons are then used to increase or decrease the number.

Once the required wavelength has been entered press the key adjacent to the tick icon to save the changes and return to the settings menu screen.

8.2.1.3 Selecting Concentration Units

The units of concentration can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μ M, nM, U, U/l, U/ml, g/l, mg/l, μ g/l, ng/l, μ g/l, mg/dl, μ g/dl, mg/ml, μ g/ml, μ g/ml, μ g/ μ l, μ l,



Press the key below the units icon and use the keys adjacent to the arrow icons to navigate round the screen to select the required units. Once the required units have been selected press the key adjacent to the tick icon to save and return to the settings menu screen.

8.2.1.4 Changing the Resolution

The resolution of the concentration can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon.


8.2.1.5 Selecting the Number of Replicate Standard Measurements

The number of replicate measurements made for each standard that is used to construct the calibration curve is set by pressing the key next to the replicate measurements icon. The number of replicates can be set to 1 or 3. When 3 replicates measurements are made, the average reading is used to construct the calibration curve. If 1 is selected, no additional measurements are performed.

8.2.1.6 Selecting Automatic or Manual Replicate Measurements


The replicate measurements of a standard are performed automatically when the automatic measurement icon is shown in the instrument settings. The replicate measurements will be repeated automatically one after another on the same standard sample. Pressing the key next to this icon changes it to the manual measurement icon where the unit will require the user to manually commence each replicate standard measurement. This feature allows users to use three independently prepared standard solutions for each data point in the calibration curve.

8.2.1.7 Selecting Number of Standards



The number of standards used to create a standard curve can be changed from 2 to 12 standards. To change the number of standards, press the key below the number of standards icon. Repeat presses cycle the number between 2, 3, 4, 5, 6, 7, 8, 9, 10, 11 and 12. If there is only one standard available the concentration measurement mode should be used.

8.2.2 Quantitation Table



The quantitation table enables the quantitation standards to be viewed and edited and allows a new calibration curve to be created. To access the quantitation table screen press the key adjacent to the quantitation table icon in the operating menu.

Mada 📉		Abs 🗸
0.10	1	0.100
0.20	2	0.200
0.30	3	0.300
- \$	⊕12	


Only three standards can be displayed on the screen at one time; to view the other standards in the table press the key below the down arrow icon. The quantitation table displays the standard concentration on the left hand side of the table with the corresponding absorbance or % transmittance on the right hand side of the table. The standard curve can also be accessed from this screen by pressing the key adjacent to the standard curve icon.

To change the number of standards, press the key below the number of standards icon. Repeat presses cycle the number between 2, 3, 4, 5, 6, 7, 8, 9, 10, 11 and 12.


8.2.2.1 Editing Standard Data

/ ppm		Abs 🗸
0.10	1	0.100
0.20	2	0.200
0.30	3	0.300
1	₽ 0 12	

This function enables the concentration and Abs/%Transmission data for each standard to be edited before a standard curve is created. To enter the concentration of the first standard, press the key adjacent to the first concentration in the table.




This opens a number entry screen; use the keys at the bottom of the screen to select the digit to be changed, pressing the key twice to select the second digit. Use the keys adjacent to the arrow icons to increase or decrease the number. Once the required number has been entered press the key adjacent to the tick icon to save the changes.




The photometric values of the standards can also be entered if known. To enter the photometric value press the key adjacent to the photometric value in the table that corresponds to the relevant concentration; this opens the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. The positive sign can be changed to a negative

sign by pressing the key below the + icon and using the keys adjacent to the arrow icons. Once the required number has been entered press the key adjacent to the tick icon to save. Standards 4-12 are accessed by pressing the key below the arrow icon and when the standard data for all the required standards has been set press the key adjacent to the tick icon to save and return to the operating menu.


8.2.2.2 Creating a New Standard Curve




Before creating a new curve it is necessary to enter the concentrations of the standard solutions in the quantitation table. Also the number of standards should be selected in the quantitation settings menu. A new standard curve can be created by pressing the key below the measure standards icon.




Confirmation will be needed to delete the existing standard data before new standard values can be measured. Press the key adjacent to the cross icon to cancel deletion and return to the quantitation table screen or press the key adjacent to the tick icon to confirm.




This will open the standard measurement screen. The first sample to be measured should be a blank sample as this will be used to calibrate the instrument to zero absorbance. Place the cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key adjacent to the tick icon to perform an initial calibration to zero absorbance. Once this measurement has been performed the standard concentration samples can be measured.



Remove the cuvette containing the blank solution from the sample chamber and insert the cuvette containing the first standardised solution to be measured. Close the instrument lid and press the key adjacent to the tick icon to take a reading of the standard.



The concentration along with the photometric value will then be displayed. This standard can be re-measured by pressing the key adjacent to the back icon.




If replicate measurements have been selected in the quantitation settings menu, a summary of the replicate measurements and the final average reading are displayed on the screen. If the manual replicate measurements setting was selected, the user is required to press the key adjacent to the tick icon to measure each replicate standard reading.


To measure the next standard remove the current standard from the sample chamber and insert the cuvette containing the second standardised solution. Press the key adjacent to the tick icon to take a reading of the standard. Repeat this procedure until all the standards (up to a maximum of twelve) have been measured. Once all the standards have been measured the instrument returns to the quantitation table screen where the photometric values for all of the newly added standards can be viewed.

To abort the creation of the new standard curve before all the standards have been measured, press the key adjacent to the cross icon at any time.

8.2.3 Standard Curve



This function enables the current standard curve to be viewed, a new standard curve to be created, the curve fit to be adjusted and the curve statistics to be displayed. To access this function press the key adjacent to the standard curve icon in the operating menu.



When the current standard curve is displayed the concentration and photometric value of the last sample measured is also displayed on the curve. The curve fit algorithm can be changed by pressing the key below the curve fit icon.

Repeat presses of the key cycles the curve fit between


1. Linear Regression

2. Linear Regression Through Zero

3. Quadratic Regression

4. Quadratic Regression Through Zero

5. Interpolate



Concentration = Abs x A + B

Concentration = Abs x A

Concentration = $A \times Abs^2 + B \times Abs + C$

Concentration = $A \times Abs^2 + B \times Abs$


Concentration(n) = Abs x A(n) + B(n)

The curve statistics can be displayed by pressing the key below the Σ icon; this opens a screen on top of the existing curve displaying statistics for the curve fit chosen. For example if the curve fit is Conc = Abs x A + B the curve statistics displayed will be the gradient of the line (A), constant (B) and correlation coefficient (r^2). To exit this screen press the key adjacent to the tick icon. The quantitation table can also be viewed from this screen by pressing the key adjacent to the quantitation table icon.

A new standard curve can be created by pressing the key below the measure standards icon. See section 8.2.2.2 for details on creating a new standard curve.

Once the curve has been created press the key adjacent to the tick icon and the screen will return to the operating menu where unknown samples can be measured.


8.3 CALIBRATION



The zero calibration must be performed at the same wavelength as the standards were measured at and the unknown samples will be measured at. Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Once the calibration is complete the measure sample icon appears and the sample can be measured. If

the wavelength is adjusted before a sample is measured the measure sample icon will disappear and the instrument must be calibrated again at the new wavelength.


8.4 SAMPLE MEASUREMENT



Once a calibration has been performed the measure sample icon appears. A standard curve should either be created or loaded from a previously saved method before carrying out a measurement of an unknown sample. Place the cuvette containing the sample in the sample chamber and close the instrument lid.

Press the key below the measure sample icon and the instrument will take a reading and the concentration and photometric values will be displayed on the screen. To view the position of this sample on the standard curve open the standard curve screen.

8.5 DATA ANALYSIS




In quantitation the data analysis examines the statistics of the standard curve and algorithm of the curve fit. The curve statistics function is accessed by pressing the key below the Σ icon in the quantitation curve menu. The algorithm of the curve fit can be changed by pressing the key below the curve fit icon. For more information regarding curve fit and statistics refer to section 8.2.3.

SECTION 9 – Kinetics


The kinetics measurement mode enables the absorbance or % transmittance of an active molecule to be measured over a period of time; for example enzyme analysis of horseradish peroxidase. The absorbance or % transmittance is measured at regular time intervals at a set wavelength over a period of time. The results are plotted on a graph to show the change in absorbance or % transmittance over time. Following sample measurement statistical analysis of all or part of the experiment can be performed.

9.1 MODE SPECIFIC PARAMETERS



The kinetics operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.


The settings icon enables the wavelength, units, resolution, graph y-axis, absorbance or % transmittance operating mode, standard, factor, measurement time, lag time and start on level to be set. Following the completion of a set of kinetics measurements the statistics for all or part of the kinetics run can be analysed. The kinetics moving line function enables the initial and final points of the curve to be selected,



so that analysis of the area between these two points can be performed.

Fig 9.1.1 - Expanded Operating Menu – Post Measurement

9.2 METHOD SET UP



In this measurement mode all the method set up parameters are accessed through the settings menu. To open the settings menu press the key adjacent to the settings icon in the operating menu.

9.2.1 Kinetics Settings

The settings menu enables the wavelength, units, resolution, graph y-axis, operating mode, standard, factor, measurement time, lag time and start on level to be set. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.






Fig 9.2.1.1 - Settings Menu

9.2.1.1 Y-Axis Scaling


This function enables the scale of the y-axis of the kinetics graph to be adjusted either manually or automatically. The automatic scaling is represented by the hand icon with a cross through it and the manual scaling by the hand icon without the cross. To select manual or automatic scaling press the key adjacent to the hand icon. Repeat pressing of the key cycles between manual and automatic scaling.




In automatic y-axis scaling the absorbance or % transmittance values are cleared from the settings screen. When the kinetics measurement is complete the y-axis is automatically re-scaled.



In manual scaling the minimum and maximum absorbance or % transmittance values can be set. To change the absorbance or % transmittance values press the key adjacent to the minimum y-axis value, this opens a number entry screen.




Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. To change the sign press the key below the + or - icon. Repeat presses will cycle between + and –. Once the required absorbance or % transmittance value has been entered press the key adjacent to the tick icon.



To change the maximum absorbance or % transmittance value press the key adjacent to the maximum y-axis value and this opens a number entry screen. Use the keys adjacent to the arrow icons to increase or decrease the number. To change the sign press the key below the + or icon. Repeat presses will cycle between + and –. Once the required absorbance or % transmittance has been entered press the key adjacent to the tick icon.


9.2.1.2 Setting Lag Time or Start on Level

In this measurement mode starting the kinetics measurements can be delayed by setting a lag time or a start on level. The lag time is the amount of time that the instrument will wait before starting the kinetics measurements. The start on level is the absorbance level that must be reached before starting the kinetics measurements. Both options can be set using the set lag time/start on menu. This function is accessed by pressing the key below the start time pause icon on the far left side of the x-axis. This opens the lag time/start on level menu.



To set the lag time press the key adjacent to the clock icon. Use the keys at the bottom of the screen to select the digit to be changed and the keys adjacent to the arrow icons to increase or decrease the number. The lag time can be reset to zero by pressing the key adjacent to the 000 icon.

Once the required lag time has been entered in seconds press the key adjacent to the tick icon to save and return to the settings menu.



To set the start on level press the key adjacent to the Abs/%T icon. Use the keys at the bottom of the screen to select the digit to be changed and the keys adjacent to the arrow icons to increase or decrease the number. The positive sign can be changed to a negative sign by pressing the key below the symbol + icon.

On the left hand side of the screen the symbol can be changed to read greater than (>) or less than (<) the absorbance level that has been entered. The start on level can also be turned off (</>). Once the required absorbance or % transmittance level (depending on the operating mode selected) has been entered press the key adjacent to the tick icon to save and return to the settings menu.

9.2.1.3 Selecting Absorbance or % Transmittance


The operating mode is displayed on the left hand side of the screen. The default parameter is absorbance and pressing the key adjacent to the ABS icon cycles the operating mode between the absorbance and % transmittance.

9.2.1.4 Changing the Resolution

The resolution of the concentration can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon.


9.2.1.5 Selecting Concentration Units

The concentration units can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μM, nM, U, U/l, U/ml, g/l, mg/l, μg/l, ng/l, mg/dl, μg/dl, mg/ml, μg/ml, μg/ml, μg/μl, ng/μl, mol/l, mmol/l.



In the settings menu press the key below the units icon to open the unit selection screen which displays all the different unit options. Use the keys adjacent to the arrow icons to navigate around the screen to select the required units. Once the required units have been highlighted press the key adjacent to the tick icon to save and return to the settings menu.

9.2.1.6 Using a Standard




The standard menu enables the value for a standard to be entered. This function is accessed by pressing the key adjacent to the standard icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digit must be pressed twice to select the adjacent digit. For example 00, the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to

increase or decrease the selected number. Standard values of 0.001 to 1000 can be entered. The standard value can be reset to one by pressing the key adjacent to the 001 icon. Once the standard value has been entered press the key adjacent to the tick icon to save and return to the settings menu screen. The entered value is now displayed in the settings menu adjacent to the standard icon.

A standard value should only be entered if the factor is not known. If the factor is known the standard value should be set to 1.000.


9.2.1.7 Using a Factor



The factor menu enables a factor to be entered. This function is accessed by pressing the key adjacent to the factor icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digit must be pressed twice to select the adjacent digit.


For example 00, the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Factor values of 0.001 to 10,000 can be entered. The factor value can be reset to one by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu screen. The entered value is now displayed in the settings menu adjacent to the factor icon. If the factor is not known a standard should be measured in order to calculate the factor. If a standard is used the factor value should be set to 1.000.

9.2.1.8 Selecting a Wavelength




To adjust the wavelength press the key adjacent to the wavelength icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed, pressing the key twice to select the second digit. The keys adjacent to the arrow icons can be used to increase or decrease the number. Once the required wavelength has been entered press the key adjacent to the tick icon to save the changes and return to the settings menu screen.

9.2.1.9 Setting the Kinetics Measurement Time



This function enables the measurement time for the kinetics scan to be set. To access this function press the key below the time displayed on the far right of the x-axis; this will open a number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. Once the required measurement time in seconds has been entered press the key adjacent to the tick icon to save and return to the settings menu.


9.3 CALIBRATION




The calibration must be performed at the same wavelength at which the sample will be measured. Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to 0.000 absorbance.

Once the calibration is complete the start kinetics measurement icon will be displayed and a sample can be measured. If the wavelength is adjusted before the sample is measured the start kinetics measurements icon will disappear and the instrument must be calibrated again at the new wavelength.


9.4 SAMPLE MEASUREMENT



Insert a cuvette containing the sample to be analysed into the sample chamber and press the key below the start kinetics measurements icon. If a start on level or lag time has not been set the instrument begins taking a photometric reading every second. As each reading is taken it is plotted on the graph.




If a lag time has been set a progress bar will be displayed showing the lag time counting down. Once the lag time is complete the instrument will begin taking readings.



If a start on level has been set the Abs/%T icon is displayed in the centre of the screen. The instrument will take photometric readings until the start on level is reached. Once the absorbance/% transmittance level has been reached the readings will be plotted on the graph.

Once the measurement has commenced it can be aborted by pressing the key below the kinetics measurement in progress icon.




Depending on how many data points have been recorded, the instrument will either return to the pre-measurement screen or display a partial scan.


Once the measurement time is reached the experiment is complete and the post measurement icons are displayed. If the automatic scaling was selected the y-axis will automatically be re-scaled.

9.5 DATA ANALYSIS

Following the completion of the kinetics measurements the post measurement icons are displayed on the screen. These include the statistics for the kinetics experiment and the kinetics moving line. The post measurement statistics include rate of change, start and end absorbance levels and concentration of the sample. The kinetics moving line function enables the initial and final points of the experiment to be set and the statistics for this part of the experiment to be analysed.



To access the statistics for the whole of the kinetics experiment press the key adjacent to the Σ icon which opens the statistics menu over the top of the expanded operating menu.




The information displayed includes concentration, absorbance per minute (rate of change), correlation coefficient (r²), start time absorbance and end time absorbance. If the operating mode selected was % transmittance then the statistics displayed will be % transmittance instead of absorbance.


In this menu the factor can be updated by pressing the key adjacent to the factor icon. The instrument calculates the factor and saves the value in the settings. Therefore the factor value calculated can be used in subsequent measurements to calculate the concentration of unknown samples.

To exit the statistics menu press the key adjacent to the tick icon.

The kinetics moving line screen can also be accessed from this menu by pressing the key adjacent to the kinetics moving line icon. The kinetics moving line function enables the initial and final points of the kinetics experiment to be set, allowing the statistics for this part of the experiment to be analysed specifically. This function can be accessed from the statistics menu or from the operating menu by pressing the key adjacent to the kinetics moving line icon.




In the kinetics moving line screen the initial and final time lines appear as two vertical lines. The line which is selected is represented by a dashed line ---- and can be moved using the keys below the greater than (>) or less than (<) icons at the bottom of the screen.



Move the dashed line to the point on the x-axis which is to be the initial time. To select the final time press the key adjacent to the toggle icon. This will change the initial line from a dashed line to a solid line. The final time line will change from a solid line to a dashed line. Use the keys below the greater than (>) or less than (<) icons to move the line to the final time on the x-axis by reducing or increasing in 1 second time intervals.

The double greater than (>>) or double less than (<<) icons move the line in 5 second time intervals.




Once the required initial and final times have been selected press the key adjacent to the Σ icon to display the statistics menu for that portion of the experiment. The information displayed includes concentration, absorbance per minute (rate of change), correlation coefficient (r^2), start time absorbance and end time absorbance. If the operating mode selected was % transmittance then the statistics will be % transmittance instead of absorbance. To exit the statistics menu press the key adjacent to the tick icon.

SECTION 10 – Multi-wavelength

The multi-wavelength measurement mode allows the user to measure a sample's photometric absorbance or %transmittance at two, three or four wavelengths. The mode allows the user to select from a number of pre-set equations to add, subtract, multiply or divide the photometric readings. Following sample measurement, the photometric readings and the selected equation's result are displayed on the operating menu screen.

10.1 MODE SPECIFIC PARAMETERS



Operating Menu

multi-wavelength operating menu measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.

The Abs/%T icon enables the display to be set to show the absorbance or % transmittance. To change the display press the key adjacent to the Abs/%T icon. Repeat presses will cycle the display between absorbance and % transmittance.

The settings icon enables the wavelengths, number of wavelengths, units, resolution, concentration calculation equation and concentration equation factors to be set.





Fig 10.1.1 - Operating Menu

10.2 **METHOD SET UP**



In this measurement mode all the method set up parameters are accessed through the settings menu. To open the settings menu press the key adjacent to the settings icon in the operating menu.

10.2.1 Multi-Wavelength Settings

The settings menu enables the wavelengths, number of wavelengths, units, resolution, concentration calculation equation and concentration equation factors to be set. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.





Fig 10.2.1.1 - Settings Menu

10.2.1.1 Setting the Number of Wavelengths

The number of measurement wavelengths can be selected by pressing the key adjacent to the number of wavelengths selection icon. Repeat presses cycle the number of wavelengths through 2, 3 and 4.

10.2.1.2 Setting the Measurement Wavelengths




To adjust the measurement wavelengths press the key adjacent to the required wavelength number icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed, pressing the key twice to select the second digit. Use the keys adjacent to the arrow icons to increase or decrease the number. Once the required wavelength has been entered press the key adjacent to the tick icon to save the changes and return to the settings menu screen.

10.2.1.3 Changing the Resolution

The resolution of the concentration can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon.


10.2.1.4 Selecting Concentration Units

The concentration units can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μ M, nM, U, U/l, U/ml, g/l, mg/l, μ g/l, mg/l, μ g/l, mg/dl, μ g/dl, mg/ml, μ g/ μ l, mol/l, mmol/l.



In the settings menu press the key below the units icon to open the unit selection screen which displays all the different unit options. Use the keys adjacent to the arrow icons to navigate around the screen to select the required units. Once the required units have been highlighted press the key adjacent to the tick icon to save and return to the settings menu.


10.2.1.5 Setting the Concentration Calculation Equation and Factors



In the settings menu press the key adjacent to the concentration calculation/factors icon. This screen allows the user to select the required concentration calculation equation from the following list of options.

- 1. $\sum = ((xF1*\lambda 1) + (x F2*\lambda 2))*xF3$
- 2. $\sum = ((xF1*\lambda 1) (x F2*\lambda 2))*xF3$
- 3. $\Sigma = ((xF1*\lambda 1) * (x F2*\lambda 2))*xF3$
- 4. $\Sigma = ((xF1*\lambda 1) / (x F2*\lambda 2))*xF3$


Repeat presses of the key adjacent to concentration calculation icon the will cycle between the options.



The concentration equation factors can be edited by pressing the key adjacent to the concentration factor icons. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit. For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease

the selected number. Factor values of 0.001 to 9999.999 can be entered. The factor value can be reset to one by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the factor icon.


10.3 CALIBRATION



Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. This will measure the zero absorbance level at each of the wavelengths specified in the method settings.

Once the calibration is complete the measure sample icon appears and the sample can be measured. If one or more wavelengths are adjusted before a sample is measured, the measure sample icon will disappear and the instrument must be calibrated again at the new wavelengths.

10.4 SAMPLE MEASUREMENT




Insert a cuvette containing the sample to be analysed into the sample chamber and press the key below the sample measurement icon. The instrument will take a reading at each of the specified wavelengths, the operating menu screen will then display the result of the selected measurement calculation and the photometric readings for each of the measured wavelengths.

LIFE SCIENCE MENU OPTIONS SECTION 11 – Concentration Plus

The concentration plus measurement mode enables simple measurements of absorbance, %transmittance and concentration to be performed. In this measurement mode it is possible to calibrate against a standard of a known concentration or use a known factor. The sample is measured at one wavelength at one point in time. There are no post measurement calculations available in this measurement mode.

11.1 MODE SPECIFIC PARAMETERS



The concentration plus operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17. The settings icon enables the wavelength, units, resolution, standard, factor and dilution factor to be set.

The Abs/%T icon enables the display to be set to show the absorbance or % transmittance. To change the display press the key adjacent to the Abs/%T icon. Repeat presses will cycle the display between absorbance and % transmittance.





Fig 11.1.1 - Operating Menu

11.2 METHOD SETUP

11.2.1 Selecting a Wavelength – Operating Menu



The wavelength can be adjusted in the operating menu or in the settings menu. To adjust the wavelength in the operating menu, use the keys adjacent to the arrow icons to increase or decrease the wavelength.

11.2.2 Concentration Plus Settings

The concentration plus settings menu enables the wavelength, units, resolution, standard, factor and dilution factor to be set and is accessed from the operating menu by pressing the key adjacent to the settings icon. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.






Fig 11.2.2.1 - Settings Menu

When setting the method parameters either the standard value or a factor should be entered. The standard should be used if the factor is not known as selecting this option will calculate the factor. If the factor is known it is not necessary to measure a known standard's concentration. When the standard or factor is not being used the value should be set to 1.00.

11.2.2.1 Selecting a Wavelength – Concentration Plus Settings




The wavelength can be adjusted in the settings menu by pressing the key below the wavelength icon. This will open a number entry screen.



Use the keys at the bottom of the screen to select the digit to be adjusted. The key below the digits must be pressed twice to select the adjacent digit. Use the keys adjacent to the arrow icons to increase or decrease the wavelength to the required number. Press the key adjacent to the tick icon to save the changes and return to the settings menu.

11.2.2.2 Selecting Concentration Units

The units of concentration can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μ M, nM, U, U/l, U/ml, g/l, mg/l, μ g/l, ng/l, μ g/dl, mg/dl, μ g/ml, μ g/ml, μ g/ μ l, ng/ μ l, mol/l, mmol/l.




In the settings menu press the key below the units icon. This opens the unit selection screen which displays all the different units. Use the keys adjacent to the arrow icons to navigate around the screen to select the required units. Once the required units have been highlighted press the key adjacent to the tick icon to save and return to the settings menu. The selected unit will be displayed in the operating menu along with absorbance and selected wavelength.

11.2.2.3 Changing the Resolution

The resolution that the concentration is displayed as can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon in the settings menu.

11.2.2.4 Using a Standard




The standard menu enables the value of a standard to be entered. This function is accessed by pressing the key adjacent to the standard icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.

For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Standard values from 0.001 to 1000 can be entered. The standard value can be reset to one by pressing the key adjacent to the 001 icon. Once the standard value has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the standard icon.

A standard value should only be entered if the factor is not known. If the factor is known the standard value should be set to 1.000.

11.2.2.5 Using a Factor





The factor menu enables a factor to be entered. This function is accessed by pressing the key adjacent to the factor icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.


For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Factor values of 0.001 to 10,000 can be entered. The factor value can be reset to one by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the factor icon.


If the factor is not known a standard should be measured in order to calculate the factor. If a standard is used the factor value should be set to 1.000.

11.2.2.6 Setting the Dilution Factor










In the settings menu press the key adjacent the dilution icon. This screen allows the user to input the relative sample and diluent volumes which have been used to prepare the sample being measured. Using this information, the instrument calculates a dilution factor which allows the instrument to determine and display the concentration of the original undiluted sample.

The volume of sample is entered by pressing the key adjacent to the sample volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. The value can be reset to one by pressing the key adjacent to the 001 icon. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.

The volume of diluent is entered by pressing the key adjacent to the diluent volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. The value can be reset to zero by pressing the key adjacent to the 000 icon. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.

After the sample and diluent volumes have been entered the dilution factor screen will show a summary of the dilution information entered.

11.3 CALIBRATION




In the concentration plus measurement mode calibrations against a standard or a factor can be performed following a zero calibration. If the factor is not known calibration against a known standard is performed in order to calculate the factor. However if the factor is known there is no need to calibrate using a standard.

The calibration must be performed at the same wavelength at which the sample will be measured.

11.3.1 Calibrating to a Standard


Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance.

Insert a cuvette containing the standard concentration sample solution into the sample chamber and close the instrument lid.




Press the key below the calibrate to zero absorbance or standard icon, this will open another menu with the option to re-calibrate to zero absorbance or to calibrate to the previously entered standard value. Press the key adjacent to the calibrate to standard icon.

If the standard selected requires a factor beyond the range of the instrument the check standard icon will be displayed.



The instrument will take a reading and calibrate to the standard concentration. Once the calibration is complete the sample can be measured using the measure to standards icon.

11.3.2 Calibrating to a Factor




Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Once the calibration is complete the sample can be measured using the measure to factor icon.

11.4 SAMPLE MEASUREMENT


It is not possible to perform sample measurements before the instrument has been calibrated at the selected wavelength. In this operating mode the type of sample measurement performed depends on the calibration which has been carried out.

11.4.1 Measuring a Sample After Calibrating to a Standard



Remove the cuvette containing the standard sample and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to standard icon. Once the measurement is complete the concentration and absorbance values are displayed.

11.4.2 Measuring a Sample After Calibrating to a Factor



Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to factor icon. Once the measurement is complete the concentration and absorbance values are displayed.

In order to measure a sample based on a known factor the value for the factor must be entered in the settings menu before commencing measurement of the sample.


SECTION 12 – Purity Scan

The purity scan measurement mode enables measurements of absorbance or % transmittance over a range of wavelengths to be performed. The absorbance or % transmittance at each wavelength is plotted graphically. Post measurement tools such as peaks and valleys analysis and spectral points analysis can be performed. This operating mode can be used to check the peak purity of a nucleic acid sample. This measurement mode's setup and operations are described in Section 7 of this manual.

SECTION 13 – Multi-wavelength plus

The multi-wavelength plus measurement mode allows the user to determine the concentration of a sample using photometric readings at more than one wavelength. The mode will also show the ratio of two readings; a reading that is commonly used to indicate the purity nucleic acids. The mode includes an option to include a reference wavelength measurement in the available calculations. Following sample measurement, the concentration and ratio calculations are displayed on the operating menu screen.

13.1 MODE SPECIFIC PARAMETERS



Operating Menu

The multi-wavelength plus operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.

The settings icon enables the wavelengths, number of wavelengths, units, resolution, dilution factor, concentration calculation equation and concentration equation factors to be set. Following the completion of a multi-wavelength measurement the calculation icon will display the expanded calculations for the results shown on the operating menu screen and the individual photometric readings.





Fig 13.1.1 - Operating Menu

13.2 METHOD SET UP



In this measurement mode all the method set up parameters are accessed through the settings menu. To open the settings menu press the key adjacent to the settings icon in the operating menu.

13.2.1 Multi-wavelength Plus Settings

The settings menu enables the wavelengths, number of wavelengths, units, resolution, dilution factor, concentration calculation equation and concentration equation factors to be set. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.





Fig 13.2.1.1 - Settings Menu

13.2.1.1 Setting the Measurement Wavelengths




To adjust the measurement wavelengths press the key adjacent to the required wavelength number icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed, pressing the key twice to select the second digit. Use the keys adjacent to the arrow icons to increase or decrease the number. Once the required wavelength has been entered press the key adjacent to the tick icon to save the changes and return to the settings menu screen.

13.2.1.2 Changing the Resolution

The resolution of the concentration can be selected from 1, 0.1, 0.01 or 0.001 by repeat presses of the key below the resolution icon.


13.2.1.3 Selecting Concentration Units


The concentration units can be selected from a number of options: no units, %, ppm, EBC, SRM, mEq/l, mEq, M, mM, μ M, nM, U, U/l, U/ml, g/l, mg/l, μ g/l, mg/l, μ g/l, mg/dl, μ g/dl, mg/ml, μ g/ml, μ g/ μ l, mol/l, mmol/l.





In the settings menu press the key below the units icon to open the unit selection screen which displays all the different unit options. Use the keys adjacent to the arrow icons to navigate around the screen to select the required units. Once the required units have been highlighted press the key adjacent to the tick icon to save and return to the settings menu.

13.2.1.4 Setting the Dilution Factor









In the settings menu press the key below the dilution icon. This screen allows the user to input the relative sample and diluent volumes which have been used to prepare the sample being measured. Using this information, the instrument calculates a dilution factor which allows the instrument to determine and display the concentration of the original undiluted sample.

The volume of sample is entered by pressing the key adjacent to the sample volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.


The volume of diluent is entered by pressing the key adjacent to the diluent volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.

After the sample and diluent volumes have been entered the dilution factor screen will show a summary of the dilution information entered.

13.2.1.5 Setting the Reference Wavelength

The reference wavelength will be included in the concentration and ratio calculations when the reference wavelength icon is showing a tick. When enabled, an additional 4th wavelength will become available to the user to edit. The wavelength of the reference measurement can be edited in the same manner as described in section 13.2.1.1.

13.2.1.6 Setting the Concentration Calculation Equation and Factors



In the settings menu press the key adjacent to the concentration calculation icon. This screen allows the user to select the required concentration calculation equation from the following list of options:


1.
$$\sum = xF1*\lambda 1$$

2.
$$\sum = (xF1*\lambda_1) - (xF2*\lambda_2)$$

When a reference wavelength is included these equations are modified as follows:

- 1. $\Sigma = xF1*(\lambda_1-\lambda_4)$
- 2. $\sum = (xF1*(\lambda_1-\lambda_4)) (xF2*\lambda_2)$


Repeat presses will cycle through the options available.



The concentration equation factors can be edited by pressing the key adjacent to the concentration factor icons. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit. For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease

the selected number. Factor values of 0.001 to 9999.999 can be entered. The factor value can be reset to one by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the factor icon.

13.3 CALIBRATION




Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. This will measure the zero absorbance level at each of the wavelengths specified in the method settings.

Once the calibration is complete the measure sample icon appears and the sample can be measured. If the wavelength is adjusted before a sample is measured the measure sample icon will disappear and the instrument must be calibrated again at the new wavelength.

13.4 SAMPLE MEASUREMENT



Insert a cuvette containing the sample to be analysed into the sample chamber and press the key below the sample measurement icon. The instrument will take a reading at each of the specified wavelengths and will then show the calculated concentration and ratio values on the operating menu screen.




Additional information can be viewed by pressing the key adjacent to the calculation icon. The screen will show the photometric readings at each of the specified wavelengths and the full concentration and ratio calculations.

SECTION 14 – DNA

The DNA measurement mode allows the user to select a method from a list of common nucleic acid measurement tests, including single wavelength concentration measurements for dsDNA, ssDNA, RNA and Oligonucleotides and methods that use absorbance ratios for estimating nucleic acid purity, such as 260nm/280nm and 260nm/230nm.


14.1 DNA MENU OPTIONS



Menu Options


The DNA menu allows the user to select the required pre-defined method from the list of on-screen options by pressing the key adjacent to the measurement method that is required. The dsDNA, ssDNA, RNA and Oligo options are used to determine the concentration of nucleic acid samples and the 260/280, 260/230 and VarRatio methods are used to assess both the purity and concentration of nucleic acids.

14.2 dsDNA



The dsDNA operating menu enables the concentration of double stranded DNA to be determined according to the equation:-


Concentration (μ g/ml) = Abs@260nm x 50.0.



The dsDNA settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution. Other method settings can be altered if required, but the concentration units are limited to $\mu g/ml$ and mg/ml only.


The dsDNA method settings are locked and any changes will be lost after exiting the mode. See Section 11 for full instructions on altering the dsDNA menu options and settings.

14.3 ssDNA



The ssDNA operating menu enables the concentration of single stranded DNA to be determined according to the equation:-


Concentration (μ g/ml) = Abs@260nm x 37.0.



The ssDNA settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution. Other method settings can be altered if required, but the concentration units are limited to μ g/ml and μ g/ml only.

The ssDNA method settings are locked and any changes will be lost after exiting the mode. See Section 11 for full instructions on altering the ssDNA menu options and settings.

14.4 RNA



The RNA operating menu enables the concentration of RNA to be determined according to the equation:-

Concentration (μ g/ml) = Abs@260nm x 40.0.




260 nm

The RNA settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution. Other method settings can be altered if required, but the concentration units are limited to $\mu g/ml$ and mg/ml only.


The RNA method settings are locked and any changes will be lost after exiting the mode. See Section 11 for full instructions on altering the RNA method options and settings.

14.5 OLIGONUCLEOTIDES



The oligonucleotide operating menu enables the concentration of a typical oligonucleotide to be determined according to the equation:-


Concentration (μ g/ml) = Abs@260nm x 30.0.




The oligonucleotide settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution. Other method settings can be altered if required, but the concentration units are limited to μ g/ml and μ g/ml only.

The oligonucleotide method settings are locked and any changes will be lost after exiting the mode. See Section 11 for full instructions on altering the oligonucleotide method options and settings.

14.6 260 / 280




Operating Menu




Purity Ratio = Abs@260nm / Abs@280nm

Conc (μ g/ml) = (Abs@260nm x 62.9) - (Abs@280nm x 36.0)




The 260/280 settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution but the concentration units are limited to µg/ml and mg/ml only. Other method settings, such as the inclusion of a reference wavelength and the concentration equation and factors can be altered if required, but the 260/280 method settings are locked and any changes will be lost after exiting the mode. See Section 13 for full instructions on altering the 260/280 method options and settings.

14.7 260 / 230



Operating Menu




The 260/230 operating menu enables the purity and concentration of DNA to be estimated according to the following equations:-

Purity Ratio = Abs@260nm / Abs@230nm

Conc (µg/ml) = (Abs@260nm x 49.1) - (Abs@230nm x 3.48)

The 260/230 settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution but the concentration units are limited to µg/ml and mg/ml only. Other method settings, such as the inclusion of a reference wavelength and the concentration equation and factors can be altered if required, but the 260/280 method settings are locked and any changes will be lost after exiting the mode. See Section 13 for full instructions on altering the 260/230 method options and settings.

14.8 VARIABLE RATIO




Operating Menu

The Variable Ratio operating menu enables the purity and concentration of DNA to be estimated according to the following equations:-

Purity Ratio = Abs@Xnm / Abs@Ynm Conc (µg/ml) = (Abs@Xnm x f1) - (Abs@Ynm x f2)

Where X, Y, f1 and f2 are defined by the user.



The Variable Ratio settings menu allows the user to adjust measurement specific parameters such as the dilution factor and resolution but the concentration units are limited to μ g/ml and mg/ml only. Other method settings, such as the inclusion of a reference wavelength and the concentration equation and factors are altered by following the instructions given in Section 13. The updated method can be saved for future use by following the instructions given in Section 17.

14.9 CALIBRATION AND SAMPLE MEASUREMENT


When adjustments to the selected methods measurement parameters are complete insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon.

Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure sample (dsDNA, ssDNA, RNA, Oligonucleotide) or measure to factor icon (260/280, 260/230, Variable Ratio). Once the measurement is complete the screen will show a summary of the analysis methods results.

SECTION 15 - Protein

The protein measurement mode allows the user to select a method from a list of common protein assays, including Pierce 660, BCA, Bradford, Lowry, Biuret and Direct UV


15.1 PROTEIN MENU OPTIONS



Menu Options


The protein menu allows the user to select the required pre-defined method from the list of on-screen options by pressing the key adjacent to the measurement method that is required. The Pierce 660, BCA, Bradford, Lowry, Biuret options allow the user to construct a calibration curve that can be used to quantify the protein content of a sample. The direct UV method uses the absorbance values at 280 and 260nm to estimate the protein content of a sample according to a standard formula.

15.2 PIERCE 660 ASSAY




The Pierce 660 operating menu enables the user to perform the Pierce 660 protein assay at the specified wavelength of 660nm.

Operating Menu




The Pierce 660 settings menu allows the user to adjust measurement specific parameters such as the number of standards and result resolution. Other method settings can be altered if required, but the Pierce 660 method settings are locked and any changes will be lost after exiting the mode. See Section 8 for full instructions on altering the Pierce 660 menu options, settings and creating a new standard curve.

15.3 BCA ASSAY




Operating Menu

The BCA operating menu enables the user to perform the BCA protein assay at the specified wavelength of 562nm.




The BCA settings menu allows the user to adjust measurement specific parameters such as the number of standards and result resolution. Other method settings can be altered if required, but the BCA method settings are locked and any changes will be lost after exiting the mode. See Section 8 for full instructions on altering the BCA menu options, settings and creating a new standard curve.

15.4 BRADFORD ASSAY




The Bradford operating menu enables the user to perform the Bradford protein assay at the specified wavelength of 595nm.

Operating Menu




The Bradford settings menu allows the user to adjust measurement specific parameters such as the number of standards and result resolution. Other method settings can be altered if required, but the Bradford method settings are locked and any changes will be lost after exiting the mode. See Section 8 for full instructions on altering the Bradford menu options, settings and creating a new standard curve.

15.5 LOWRY ASSAY




The Lowry operating menu enables the user to perform the Lowry protein assay at the specified wavelength of 750nm.

Operating Menu




The Lowry settings menu allows the user to adjust measurement specific parameters such as the number of standards and result resolution. Other method settings can be altered if required, but the Lowry method settings are locked and any changes will be lost after exiting the mode. See Section 8 for full instructions on altering the Lowry menu options, settings and creating a new standard curve.

15.6 BIURET ASSAY




The Biuret operating menu enables the user to perform the Biuret protein assay at the specified wavelength of 540nm.

Operating Menu




The Biuret settings menu allows the user to adjust measurement specific parameters such as the number of standards and result resolution. Other method settings can be altered if required, but the Biuret method settings are locked and any changes will be lost after exiting the mode. See Section 8 for full instructions on altering the Biuret menu options, settings and creating a new standard curve.


15.7 DIRECT UV



Operating Menu



Purity Ratio = Abs@280nm / Abs@260nm Conc(µg/ml) = (Abs@280nm x 1550) - (Abs@260nm x 760)



The Direct UV settings menu allows the user to adjust measurement specific parameters such as the dilution factor and result resolution. Other method settings, such as the inclusion of a reference wavelength and the concentration equation/factors can be altered if required, but the Direct UV method settings are locked and any changes will be lost after exiting the mode.

See Section 13 for full instructions on altering the Direct UV method options and settings.

15.8 CALIBRATION AND SAMPLE MEASUREMENT


When adjustments to the selected methods measurement parameters are complete insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon.

Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure sample icon. Once the measurement is complete the screen will show a summary of the results.

SECTION 16 – OD 600

The OD 600 measurement mode enables optical density measurements of cell cultures and broths to be performed. In this measurement mode it is possible to use a known factor to estimate the number of cells or the user can determine the factor to be used by measuring a standard solution containing a predetermined number of cells. An instrument normalisation factor can also be applied to equate the results obtained on different spectrophotometers. The sample solution is measured at one wavelength at one point in time. There are no post measurement calculations available in this measurement mode.

16.1 MODE SPECIFIC PARAMETERS



The OD 600 operating menu enables measurement parameters to be changed. The utility toolbar on the left hand side of the screen enables access to printing, print setup options, results, methods and autologging options. For more details on the different functions of the utility toolbar refer to section 17.

Operating Menu

The settings icon enables the wavelength, units, resolution, standard concentration, concentration factor, instrument factor and dilution factor to be set.






Fig 16.1.1 - Operating Menu – After Calibration

16.2 METHOD SETUP


16.2.2 Selecting a Wavelength



The wavelength can be adjusted in the operating menu or in the settings menu. To adjust the wavelength in the operating menu use the keys adjacent to the arrow icons to increase or decrease the wavelength.



The settings menu is accessed through the operating menu by pressing the key adjacent to the settings icon. In the settings menu press the key below the wavelength icon.



This will open a number entry screen. Use the keys at the bottom of the screen to select the digit to be adjusted. Use the keys adjacent to the arrow icons to increase or decrease the wavelength to the required number. Press the key adjacent to the tick icon to save the changes and return to the settings menu.

16.2.2 Settings

The settings menu enables the wavelength, resolution, standard, factor, instrument factor or dilution factor to be set and is accessed from the operating menu by pressing the key adjacent to the settings icon. Once all of the required settings have been entered press the key adjacent to the tick icon to save and return to the operating menu.





Fig 16.2.2.1 – Settings Menu

When setting the method parameters either the standard or the factor should be selected. The standard should be used if the factor is not known as selecting this option will calculate the factor. If the factor is known it is not necessary to measure a known standard's concentration. When the standard or factor is not selected the value should be set to 1.00.

16.2.2.1 Using a Standard




The standard menu enables the value of a standard to be entered. This function is accessed by pressing the key adjacent to the standard icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.

For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Standard values from 0.001e-19 to

9.999e+19 can be entered. The standard value can be reset to 1.000e+00 by pressing the key adjacent to the 001 icon. Once the standard value has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the standard icon.

A standard value should only be entered if the factor is not known. If the factor is known the standard value should be set to 1.000e+00.

16.2.2.2 Using a Factor




The factor menu enables a factor to be entered. This function is accessed by pressing the key adjacent to the factor icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.

For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Factor values of 0.01e-19 to 9.999e+19 can be entered. The factor value can be reset to 1.000e+00 by pressing the key adjacent to the 001 icon. Once the factor has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the factor icon.

If the factor is not known a standard should be measured in order to calculate the factor. If a standard is used the factor value should be set to 1.000e+00.

16.2.2.3 Using an Instrument Factor




The instrument factor menu enables an instrument factor to be entered to allow results from different spectrophotometers to be normalised. This function is accessed by pressing the key adjacent to the instrument factor icon. This opens the extended number entry screen. Use the keys at the bottom of the screen to select the digit to be changed. The key below the digits must be pressed twice to select the adjacent digit.


For example 00 the first press of the key alters 10, the second press alters 01. Use the keys adjacent to the arrow icons to increase or decrease the selected number. Instrument factor values from 0.001 to 9999.999 can be entered. Once the instrument factor value has been entered press the key adjacent to the tick icon to save and return to the settings menu. The entered value is displayed in the settings menu adjacent to the instrument factor icon.

An instrument factor should only be entered if the factor is known. If the factor is not known the instrument factor should be set to 1.000.


16.2.2.4 Setting the Dilution Factor




In the settings menu press the key adjacent the dilution icon. This screen allows the user to input the relative sample and diluent volumes which have been used to prepare the sample being measured. Using this information, the instrument calculates a dilution factor which allows the instrument to determine and display the concentration of the original undiluted sample.



The volume of sample is entered by pressing the key adjacent to the sample volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. The value can be reset to one by pressing the key adjacent to the 001 icon. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.




The volume of diluent is entered by pressing the key adjacent to the diluent volume icon. This will open the number entry screen. Use the keys at the bottom of the screen to select the digit to be changed and use the keys adjacent to the arrow icons to increase or decrease the number. The value can be reset to zero by pressing the key adjacent to the 000 icon. Once the required volume has been entered press the key adjacent to the tick icon to save the changes and return to the settings.



After the sample and diluent volumes have been entered the dilution factor screen will show a summary of the dilution information entered.

16.3 CALIBRATION




In the OD 600 measurement mode calibrations against a standard or a factor can be performed following a zero calibration. If the factor is not known calibration against a known standard is performed in order to calculate the factor. However if the factor is known there is no need to calibrate using a standard.

The calibration must be performed at the same wavelength at which the sample will be measured.


16.3.1 Calibrating to a Standard

Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Insert a cuvette containing the standard concentration sample solution into the sample chamber and close the instrument lid.




Press the key below the calibrate to zero absorbance or standard icon, this will open another menu with the option to re-calibrate to zero absorbance or to calibrate to the previously entered standard value. Press the key adjacent to the calibrate to standard icon.

If the standard selected requires a factor beyond the range of the instrument the check standard icon will be displayed.



The instrument will take a reading and calibrate to the standard concentration. Once the calibration is complete the sample can be measured using the measure to standard icon.

16.3.2 Calibrating to a Factor




Insert a cuvette containing the blank solution into the sample chamber and close the instrument lid. Press the key below the calibrate to zero absorbance icon. The instrument will calibrate to zero absorbance. Once the calibration is complete the sample can be measured using the measure to factor icon.

16.4 SAMPLE MEASUREMENT


It is not possible to perform sample measurements before the instrument has been calibrated at the selected wavelength. In this operating mode the type of sample measurement performed depends on the calibration which has been carried out.

16.4.1 Measuring a Sample After Calibrating to a Standard



Remove the cuvette containing the standard sample and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to standard icon. Once the measurement is complete the concentration and absorbance values are displayed.

16.4.2 Measuring a Sample After Calibrating to a Factor



Remove the cuvette containing the blank solution and place a cuvette containing the sample to be measured in the sample chamber. Close the instrument lid and press the key below the measure to factor icon. Once the measurement is complete the concentration and absorbance values are displayed.

In order to measure a sample based on a known factor the value for the factor must be entered in the settings menu before commencing measurement of the sample.

SECTION 17 – Saving, printing and autologging

The utility toolbar in the operating menu provides access to printing, print setup options, opening, saving and deleting results and methods and autologging options.

If the method lock has been activated the method selection menu is disabled.




Fig 17.1 - Operating Menu


17.1 SAVING METHODS

The number of methods that can be saved to the internal memory of the instrument is given in table 17.1. Once the method has been saved to the internal memory the method can be saved directly to a USB memory stick and opened on another instrument.


Operating Mode	Number of Methods
Photometrics	16
Concentration	16
Quantitation	16
Spectrum	16
Kinetics	16
Multi-wavelength	16
Multi-wavelength Plus	48
Concentration Plus	48
Protein	48
Purity Scan	48

Table 17.1 – Method storage capacity (Internal Memory)

17.1.1 Saving Methods To Internal Memory




In the operating menu press the key adjacent to the method icon to open the method selection menu. Select the location to save the method by pressing the key adjacent to the location. Use the keys below the arrow icons to move page up or down. Press the key below the save icon to open the method naming menu.



The default method name will be displayed. To save the method under the default name press the key adjacent to the tick icon. To change the name of the method press the key below the eraser icon. One press of the key will delete one letter, holding the key for 2 seconds will delete the name completely.


To select letters use the keys adjacent to the arrow icons to move around the menu. Once the required letter is highlighted press the key below the pencil icon to select the letter. Up to eight characters can be selected. To change the letter case or to use numbers in the method name press the key below the AB icon. Repeat pressing of this key will cycle between upper case, lower case and numbers. Once the required name for the method has been entered press the key adjacent to the tick icon to save the method and return to the method selection menu.




If there is already a method saved in the chosen location confirmation will be needed to replace the existing method with the new one; press the key adjacent to the tick icon to confirm replacement. Press the key adjacent to the cross icon to cancel and return to the method naming menu.

To exit the method naming menu without saving the method press the back key.


17.1.2 Saving Methods to USB Memory Stick



In the operating menu press the key adjacent to the method icon to open the method selection menu. Select the method to save to USB memory stick by pressing the key adjacent to the method location. Use the keys below the arrow icons to move page up or down. Hold the key below the save icon for 2 seconds to open the save to USB memory stick menu.



Either the single method selected or all 16 (or 48) methods can be saved to USB memory stick. To save a single method press the key adjacent to the single method save icon. To save all 16 (or 48) methods press the key adjacent to the 1 - 16 (or 48) method save icon. Press the key adjacent to the tick icon to confirm saving the method(s) to USB memory stick. Press the key adjacent to the cross icon to cancel saving the method(s) to USB memory stick and return to the method selection screen.




Confirmation will be needed to save the methods to USB memory stick. Press the key adjacent to the tick icon to confirm saving the method(s). Press the key adjacent to the cross icon to cancel and return to the option of saving one or all of the methods to USB memory stick.


17.2 OPENING METHODS

Methods can be opened from the internal memory of the instrument or from a USB memory stick. Before a method can be opened from a USB memory stick it must be saved to the internal memory of the instrument first.

17.2.1 Opening Methods From Internal Memory




In the operating menu press the key adjacent to the method icon to open the method selection menu and use the keys below the arrow icons to move page up or down. Select the method to open by pressing the key adjacent to the method location. Press the key below the open icon.




The instrument will return to the current measurement mode and the method name will be displayed at the top of the operating menu.

If a method hasn't been selected it is still possible to calibrate the instrument and take measurements.

17.2.2 Opening Methods From USB Memory Stick




In the operating menu press the key adjacent to the method icon to open the method selection menu and use the keys below the arrow icons to move page up or down. Select an empty location to save the method by pressing the key adjacent to the location. Hold the key below the open icon for 2 seconds.




Either a single method or all 16 methods can be opened from the USB memory stick. Select one method by pressing the key adjacent to the single method open icon. To open all methods press the key adjacent to the 1-16 (or 48) method open icon. Press the key adjacent to the tick icon to confirm selection.

Or press the key adjacent to the cross icon to cancel and return to the method selection screen.




Confirmation will be needed to open the method(s) as any existing methods in this measurement mode will be overwritten. Press the key adjacent to the tick icon to save over the existing methods. Press the key adjacent to the cross icon to cancel and return to the option of opening one or all methods from the USB memory stick. If a single method is selected to be opened, this method will be stored in the same location that is was saved in when it was originally saved to the USB memory stick.

17.3 DELETING METHODS




In the operating menu press the key adjacent to the method icon to open the method selection menu and use the keys adjacent to the arrow icons to move page up or down. Select the method to be deleted by pressing the key adjacent to the method location and press the key below the delete icon.




Confirmation will be needed to delete the selected method; press the key adjacent to the tick icon to confirm deletion. Press the key adjacent to the cross icon to cancel deletion and return to the method selection menu.

17.4 SAVING RESULTS


Results can only be saved if there is a valid USB memory stick inserted into the front of the instrument. The instruments are supplied with a USB memory stick but other types which may be used include: the PNY Attache Premium, the Emtec C250, The Kingston Data Traveler G2, the Sony Pocket Bit and the Integral Flexi.



In the operating menu press the key adjacent to the USB memory stick icon to open the results selection menu.




If the USB memory stick doesn't have any results stored on it only the save icon will be displayed. To save a result press the key below the save icon. This will open the results naming menu.




The default result name will be displayed. To save the result under the default name press the key adjacent to the tick icon. To change the name of the result press the key below the eraser icon. One press of the key will delete one letter, holding the key for 2 seconds will delete the name completely.

To select letters use the keys adjacent to the arrow icons to move around the menu. Once the required letter is highlighted press the key below the pencil icon to select the letter. Up to eight characters can be selected. To use numbers in the results name press the key below the AB icon. Repeat pressing of this key will cycle between upper case and numbers. Once the required name for the result has been entered press the key adjacent to the tick icon to save and return to the results selection menu.



The saved results are listed alphabetically with the date and time that the result was generated.


If there is already a result saved under the same name confirmation will be needed to replace the existing result with the new one. Press the key adjacent to the tick icon to confirm replacement. Press the key adjacent to the cross icon to cancel and return to the results naming menu.




In photometrics, concentration, concentration plus, multi-wavelength and quantitation once a result has been saved to the USB memory stick the USB memory stick icon will remain highlighted. Pressing the key adjacent to the highlighted icon will result in subsequent results being saved under the same file name. To save the result with a new filename hold the key adjacent to the highlighted USB memory stick icon for 2 seconds. This will open the results naming screen.

17.5 OPENING RESULTS

Results can only be opened if a valid USB memory stick is inserted into the front of the instrument.




In the operating menu press the key adjacent to the USB memory stick icon to open the results selection menu. Select the result to be opened by pressing the key adjacent to the result. Press the key below the open icon.



The result will be displayed on the screen.


The information displayed is specific to the measurement mode which the result was generated and saved in. Use the keys below the arrow icons to display more information.




When opening a spectrum or kinetics result the result can be viewed graphically on an axis or as a text file. To view the result graphically press the key adjacent to the axis icon. To view the result as a text file press the key adjacent to the ABC icon.

17.6 DELETING RESULTS

Results can only be deleted if a valid USB memory stick is inserted into the front of the instrument.




In the operating menu press the key adjacent to the USB memory stick icon to open the results selection menu. Select the result to be deleted by pressing the key adjacent to the result. Press the key below the delete icon.



Confirmation will be needed to delete the selected result; press the key adjacent to the tick icon to confirm deletion. Press the key adjacent to the cross icon to cancel and return to the results selection menu.


17.7 PRINTING



Operating Menu

The utility toolbar in the operating menu enables results to be printed and print setup options to be set. The print setup menu enables the destination of the printouts and language of the printouts to be set. Depending on the measurement mode the printouts can be customised to print off post analysis statistics.

17.7.1 Print Setup



To open the print setup menu hold the key adjacent to the printer icon for 2 seconds in the operating menu.




To select the language for the printouts press the key adjacent to English icon. Repeat pressing of the key cycles the language between English, Français, Deutsche, Espânôl and Italiano.

The destination of the printouts can be the internal printer or an external serial printer. The results can only be sent to an external serial printer if there is a serial printer connected to the instrument via the RS232 serial port. Press the key adjacent to the computer icon to select the external serial printer. The results can only be sent to the internal printer if there is an internal printer connected. To select the internal printer for the printout destination press the key adjacent to the printer icon.


Once the required printout destination and language has been selected press the key adjacent to the tick icon to save and return to the operating menu.

17.7.1.1 Print Setup – PHOTOMETRICS, CONCENTRATION, MULTIWAVELENGTH AND OD 600



In the photometrics, concentration, multiwavelength and OD 600 measurement modes the print setup menu does not contain any additional post analysis statistics.

17.7.1.2 Print Setup - SPECTRUM AND PURITY




In the spectrum and purity measurement mode print setup menu it is possible to print off the spectral points analysis table, peaks and valleys data and absorbance or %T values recorded at certain data intervals. If the data interval is set to 5 every 5th data point recorded is reported. If no data is required the data interval can be set to zero.



To select the spectral points analysis table to be printed press the key adjacent to the spectral table icon. Repeat presses of the key will cycle between a tick and a cross icon for selected or deselected. To select the peaks and valleys data to be printed press the key adjacent to the peaks and valleys icon. To select the data interval press the key adjacent to the data interval icon. Repeat presses will cycle between 0, 1, 2, 5, 10 or 50. Once the required options have been selected press the key adjacent to the tick icon to save and exit print setup.

17.7.1.3 Print Setup – QUANTITATION AND PROTEINS



In the quantitation and proteins measurement mode print setup menu it is possible to print off the statistics for the standard curve. To select the curve statistics press the key adjacent to the curve statistics icon. Repeat presses of the key will cycle between a tick and a cross icon for selected or deselected. Once the required options have been selected press the key adjacent to the tick icon to save and exit print setup.

17.7.1.4 Print Setup – KINETICS




In the kinetics measurement mode print setup menu it is possible to print off the statistics for the whole kinetics experiment and the absorbance or % transmittance values recorded at certain data intervals. If the data interval is set to 10 every 10^{th} data point recorded is reported. If no data is required the data interval can be set to zero. To select the statistics to be printed press the key adjacent to the Σ


icon. Repeat presses of the key will cycle between a tick and a cross icon for selected or deselected. To select the data interval press the key adjacent to the data interval icon. Repeat presses will cycle between 0, 1, 5, 10, 30 or 60 seconds.

Once the required options have been selected press the key adjacent to the tick icon to save and exit print setup.

17.7.2 Printing Results




Results displayed in the operating menu can be printed by pressing the key adjacent to the printer icon. Any options selected in the print setup menu will also be reported when the printer icon is pressed. Depending on the printout destination selected the result will be sent to the internal printer or to the external serial printer. If the printer icon is pressed when there is not a result on the screen the no result to printer or no result to RS232 icon (depending on results destination) will flash up on the screen.



Saved results can be printed by pressing the key below the printer icon. The printout will include the date and time the result was generated, the user ID and the measurement parameters.


17.8 AUTOLOGGING




Operating Menu

The autolog function enables repeat measurements of the same sample to be performed with a set time period between each measurement. This produces a batch of results for the same sample. The autolog function also enables the results to be autologged to different destinations. The autolog menu is accessed from the utility toolbar in the operating menu by pressing the key adjacent to the autolog icon.


17.8.1 Setting the Number of Sample Repetitions



To set the number of repeat measurements of the same sample press the key below the sample icon and use the keys adjacent to the arrow icons to increase or decrease the number of repetitions required. To reset the number to zero, press and hold the key below the sample icon for 2 seconds and release.




Once the number of repetitions is increased above zero, if the results are autologged to a USB memory stick, the batch ABC icon will be displayed. To assign a batch name for the repeated measurements press the key below the batch ABC icon to open the batch naming menu.




The default batch name will be displayed. To save the batch name under the default name press the key adjacent to the tick icon. To change the name, press the key below the eraser icon. One press of the key will delete one letter, holding the key for 2 seconds will delete the name completely. To select letters use the keys adjacent to the arrow icons to move around the menu. Once the required letter is highlighted press the key below the pencil icon to

select the letter. Up to eight characters can be selected. To use numbers in the batch name press the key below the AB icon. Repeat pressing of this key will cycle between upper case and numbers. Once the required name for the batch has been entered press the key adjacent to the tick icon to save and return to the autolog menu.




To set the time period between each measurement press the key below the timer icon and use the keys adjacent to the arrow icons to increase or decrease the time in 1 second intervals. To reset the time to one second press and hold the key below the timer icon for 2 seconds.

Once the required number of repetitions and time period has been selected press the key adjacent to the tick icon to save the changes and return to the operating menu.



The number of repetitions and time period will be displayed below the autolog icon. To commence autologging press the key below the measure sample icon. Once the first measurement has been performed the time period starts counting down until it reaches zero and then the next measurement will be taken. This will reduce the repetition number by one. When the number of repetitions reaches zero autologging is complete. Autologging can be stopped


before all the measurements have been completed by pressing the key adjacent to the autolog icon. Confirmation will be needed to stop autologging. Press the key adjacent to the tick icon to confirm stopping autologging or press the key adjacent to the cross icon to continue autologging. If autologging is stopped before completion the measurements already recorded will be saved under the previously entered batch name.



Once a set of results has been autologged to the USB memory stick when the measure sample key is pressed again the batch append/delete screen is displayed. Pressing the key adjacent to the batch append icon enables the next set of results to be added to the existing batch of results. Pressing the key adjacent to the batch delete icon will delete the first set of results and replace them with


the results that are going to be recorded. Press the key adjacent to the tick icon to confirm selection. Press the key adjacent to the cross icon to cancel and return to the operating menu.

17.8.2 Selecting Result's Destination



The autolog menu enables the result's destination to be set. To select the internal printer press the key adjacent to the printer icon. This option is only available if an internal printer is connected. To select the USB memory stick press the key adjacent to the USB memory stick icon. This option is only available if a valid USB memory stick is connected to the instrument. To send the results to an external instrument such as a PC or a serial printer press the key adjacent to the computer icon.

17.9 LOCKED METHODS



The Genova Plus spectrophotometer contains a number of standard measurement methods that cannot be deleted from the instrument. These methods are indicated by a padlock symbol before the method name.

17.10 CONNECTING TO A PC

Connect the interface cable to the RS232 serial port on the rear of the instrument and connect to the serial port on the PC. The connecting serial port should be configured with the following settings:

9600 baud

8 data bits

No parity

1 stop bit

SECTION 18 – Accessories and spare parts


18.1 OPTIONAL ACCESSORIES

Part Code	Description of Accessory
660 101	Internal printer
735 401	Automatic 8 cell turret
735 201	Sipper pump
735 301	Peltier
735 701	Combined sipper Peltier
630 204	10x10mm path length cuvette holder
637 071	16/24mm test tube holder
630 005	10 x 100mm path length cuvette holder
630 304	Micro-cuvette holder with reduced aperture
736 201	Water heated 10x10 single cell holder
035 088	Visible calibration set
035 091	UV/Visible calibration set
060 422	Moulded cuvette rack for 16 10x10mm cuvettes
735 001	Dust cover
019 146	4GB USB memory sticks for external memory
035 262	TrayCell for ultra-micro sample volumes
035 143	Pack of 100 disposable micro-cuvettes (70µl)

18.2 CONNECTING THE ACCESSORIES

There are two types of accessories which can be fitted in the sample chamber – passive or active accessories. The range of passive accessories includes 10 x 10mm single cuvette holders, single water heated cuvette holders, adjustable path length (10 to 100 mm) cuvette holders, test tube holders and micro-cuvette holders. The range of active accessories includes an automated 8 cell changer, sipper pump, Peltier and combined Peltier sipper pump. The instrument must be turned off before any accessories are fitted.

18.2.1 Internal Printer



Use a small screw driver to lift the blanking panel on the top of the instrument. Squeeze the two clips in order to remove the blanking panel. Disconnect the printer wires which are secured to the underside of the blanking plate.



Unpack the printer from the packaging. Turn the printer upside down and connect the printer wires by clipping into the connector on the printer.




Squeeze the grey plastic clips together so that the printer top opens. Slot the printer into the top of the instrument and push down until it fits flush to all four sides.



Insert the paper roll into the printer – ensuring that there is some paper sticking out of the printer before clicking the grey plastic back into place. Switch the instrument on. The power and error lights on the printer will flash. Once the instrument power on tests are complete press the feed button to check that the paper is fed correctly.

18.2.2 Passive Accessories




Unscrew the thumb screw to undo the passive accessory. Lift out the passive accessory. To fit a different passive accessory simply place the accessory in the correct orientation, align the thumb screw and tighten to fix in place.


To replace the passive accessory with an active accessory refer to section 18.2.3.

Thumb screw

18.2.3 Active Accessories




Unscrew the thumb screw to undo the passive accessory. Lift out the passive accessory. To fit an active accessory unscrew screws 1 to 4 and lift out the metal base plate.



This will expose the bottom of the sample chamber with the power supply connection needed to operate the active accessories.

18.2.3.1 Automatic 8 cell turret




Take the 8 cell turret base plate. Connect the power supply in the bottom of the sample chamber to the connector on the underside of the base plate. Place the base plate in the sample chamber. Replace screws 1 to 4.




Take the 8 cell carousel and place on top of the motor, taking care to align the three ball bearings with the grooves on the motor shaft. Gently push the carousel down onto the motor shaft until it is located into place. Gently rotate the carousel until there is some resistance. The carousel is now in the correct position.

If the fitting is too tight use a small screw driver to loosen the ball bearings before pushing the carousel down onto the shaft.


18.2.3.2 Peltier



For this accessory as well as removing the passive accessory base plate, the front panel of the instrument must also be removed. Loosen screws 5 and 6 until the front panel can be lifted out in the forwards direction.




Take the Peltier base plate. Connect the power supply in the bottom of the sample chamber to the connector on the underside of the base plate. Place the base plate in the sample chamber. Replace screws 1 to 4. Take the Peltier front panel and slot into place before retightening screws 5 and 6.




When the accessory is fitted the instrument will look like this.

18.2.3.3 Sipper pump




For this accessory as well as removing the passive accessory base plate, the front panel of the instrument must also be removed. Loosen screws 5 and 6 until the front panel can be lifted out in the forwards direction.



Take the sipper base plate. Connect the power supply in the bottom of the sample chamber to the connector on the underside of the base plate. Place the base plate in the sample chamber. Replace screws 1 to 4. Take the sipper front panel and slot into place before retightening screws 5 and 6.




Bi directional flow A (sipping) The tubing should be connected depending on the function that the sipper pump is going to perform. All tubing must be kept as short as possible and the tubing must not be allowed to obstruct the ligth path.



Bi directional flow B (pumping)




Continuous flow



For sipping:


- 1. Connect the sipper pump tubing to the outlet port on the flow-through cuvette.
- 2. Secure the tubing using the clip on the righthand side of the pump head.
- 3. Ease the tubing round the rollers by carefully rotating them clockwise, by hand. Clamp the tubing into the clip on the left hand side of the motor.
- 4. Once secured, ensure the tubing is routed into the two retaining clips located on the base plate at the side of the pump head.
- 5. Cut the tubing at the point where it fits comfortably onto the left hand tube located on the inside of the front bulk head.
- 6. Connect a suitable length of this tubing to the external waste pipe.
- 7. Cut a small length of the sipper pump tube and push this over one end of the capillary tube. Connect this to the inlet port of the flow-through cuvette.
- 8. Route the tube into the two retaining clips located on the base plate at the side of the pump head.
- 9. Fit the sipper probe and secure using the thumbscrew. Feed the capillary tubing through the tube and up through the sipper probe, allowing sufficient length for it to pass into a suitable receptacle.



For pumping:

- 1. Cut two pieces of sipper pump tubing approximately 300mm in length. Take one length of tubing and fit this to the pump head, as shown, securing the tubing using the clip on the right hand side of the pump head.
- 2. Ease the tubing round the rollers carefully rotating them clockwise, by hand. Clamp the tubing into the clip on the left hand side of the motor.
- 3. Fit the other end onto the inlet port on the flow-through cuvette.
- 4. Fit the second 300mm length of tubing to the outlet port of the flow-through cuvette. Once secured, ensure the tubing is routed into the two retaining clips located on the base plate at the side of the pump head.
- 5. Fit the other end of the tubing onto the outlet port, located on the inside of the front bulkhead.

- 6. Connect a suitable length of sipper pump tubing to the external outlet port.
- 7. Insert one end of the capillary tube into the sipper pump tubing, as shown.
- 8. Feed the other end through the inlet port located on the inside of the bulkhead.
- 9. Fit the sipper probe and secure using the thumbscrew.
- 10. Carefully feed the tubing through the sipper probe, allowing sufficient length for it to pass into a suitable receptacle.




When the sipper accessory has been fitted and the tubing has been connected the instrument will look like this.

18.2.3.4 Combined sipper Peltier pump

Refer to section 18.2.3.3 for more details.


18.3 USING THE ACCESSORIES

18.3.1 Automatic 8 cell turret



When the automatic 8 cell turret is in use the 8 cell turret icon is displayed in the bottom right hand corner of the screen. The current cell position is displayed adjacent to the 8 cell turret icon. The 0 position should always be used for the zero calibration sample.

To perform measurements using the automatic 8 cell turret, insert the cuvettes containing the samples into turret positions 1 to 7. Insert the cuvette containing the blank solution into turret position 0. Enter the required measurement mode and set up the required measurement parameters. Press the key below the calibrate to zero icon. The instrument will automatically move the turret around to position zero to perform the measurement. Once the calibration is complete the measure sample icon will appear and the turret will return to its original starting position.




Press the key below the 8 cell turret icon to highlight the icon and the two arrow icons above. Press the keys adjacent to the arrow icons to increase or decrease the current cell position of the turret, until the required sample position has been selected. Press the key below the measure sample icon. The instrument will perform a reading and display the result on the screen. To measure the next sample select the next turret position and press the key below the measure

sample icon. Repeat this process until all the samples have been measured. To adjust the wavelength press the key below the 8 cell turret icon and use the arrow icons to adjust the wavelength.

18.3.1.1 Automatic 8 cell turret – supporting creation of a standard curve in quantitation

The 8 cell turret can be used to support creation of a new standard curve in the quantitation and protein measurement modes. Refer to section 8.2.2.2 for more details.




When the standard measurement screen is open the 8 cell turret icon will be displayed in the bottom left hand corner of the screen. The current cell position is displayed adjacent to the 8 cell turret icon. The 0 position should always be used for the zero calibration sample.

To measure the standards using the automatic 8 cell turret, insert the cuvettes containing the standards into turret positions 1 to 7 (if greater than 7 standards are being used the cuvettes containing standards 8 to 12 must be inserted into the turret after the earlier standards have been measured). Insert the cuvette containing the blank solution into turret position 0. Press the key adjacent to the tick icon to perform an initial calibration to zero absorbance.


Use the keys adjacent to the arrow icons to increase the turret position, until the required standard position has been selected. Press the key adjacent to the tick icon to measure the standard. The standard concentration and photometric value will then be displayed. The standard can be re-measured by pressing the key adjacent to the back icon.

To measure the next standard select the next turret position and press the key adjacent to tick icon. Repeat this process until all the standards have been measured.


18.3.2 Peltier



When the Peltier is in use the Peltier icon is displayed in the bottom right hand corner of the screen. The current temperature is displayed above the set point temperature adjacent to the Peltier icon. An arrow icon is displayed above or below the Peltier icon depending on if the current temperature is above or below the set temperature. To adjust the set point temperature hold the key below the Peltier icon for 2 seconds.




This opens the Peltier settings screen. Use the keys at the bottom of the screen to select the digit to be changed and use the arrow icons to increase or decrease the number. The temperature can be set in °C or °F by pressing the key adjacent to the °C icon.




Repeat presses will cycle between °C and °F. Once the required temperature has been selected press the key adjacent to the tick icon to save and return to the operating menu. The Peltier will begin to heat or cool depending on the current temperature.

18.3.3 Sipper pump




When the sipper is in use the sipper pump icon is displayed in the bottom right hand corner of the screen. The sipper pump can operate in manual or timed mode, depending on the option selected in sipper pump settings. If the manual mode is selected an arrow icon indicating pump direction will be displayed below the sipper pump icon.




If the timed mode is selected a clock icon will be displayed adjacent to the sipper pump icon.

To open the sipper pump settings hold the key below the sipper pump icon for 2 seconds.


18.3.3.1 Manual Sipper Pump Settings




To operate the sipper pump in manual mode press the key adjacent to the manual sipper icon. Select the preferred pump direction by pressing the key below the forwards or backwards arrow. Press the key adjacent to the tick icon to save and return to the expanded operating menu.



To perform a measurement place the sipper tubing into the sample and press the key below the sipper pump icon.




Confirmation will be needed to start the sipper pump. Press the key adjacent to the tick icon to confirm and start the sipper pump. Press the key adjacent to the cross icon to cancel and return to the expanded operating menu.




To stop the sipper pump press the key adjacent to the stop icon. Ensure that the flow through cuvette contains enough sample before pressing the key below the measure sample icon.


18.3.3.2 Timed Sipper Pump Settings




To operate the sipper pump in timed mode press the key adjacent to the timed sipper pump icon.




Press the key below the calibrate timed sipper icon. Select the required pump direction by pressing the key below the forwards or backwards arrow. Press the key adjacent to the tick icon to continue to the next stage of the calibration sequence.




Insert the inlet tubing into the sample container and press the key adjacent to the single greater than icon. The sipper pump will start and the sample will be pumped through the tubing to the flow through cuvette. It is possible to skip this setup stage by pressing the key adjacent to the double greater than icon.



Once the cuvette is full press the key adjacent to the stop icon to stop the sipper pump. The time taken for sample uptake is recorded.




To fine tune the amount of sample uptake press the key below the plus or minus icon to increase or decrease the amount of sample taken up. The recorded time will be adjusted accordingly. Once the fine tuning is complete, or if none is required, press the key adjacent to the tick icon to move to the next stage of the calibration sequence.




This stage allows an air gap to be added to the calibration sequence. If an air gap is not required press the key below the 000 icon to set the air gap to zero. If a previously programmed air gap is to be used press the key adjacent to the double greater than icon to skip this stage and retain the current air gap time.


To program an air gap remove the inlet tubing from the sample container and press the key adjacent to the single greater than icon. The sipper pump will start and air will be pumped through the tubing to the flow through cell.



Once the required amount of air has been taken up press the key adjacent to the stop icon. The time taken for air uptake is recorded.




To fine tune the amount of air uptake press the key below the plus or minus icon to increase or decrease the amount of air taken in. The recorded time will be adjusted accordingly. Once the fine tuning is complete, or if none is required press the key adjacent to the tick icon to move to the next stage of the calibration sequence.




Once the sample uptake and air gap have been programmed the preferred disposal of the sample can be set. There are two options, the sample can either be sent back to the sample container or it can be sent to waste. Press the key below the forward or backward arrow to select what happens to the sample after measurement. If the original pump direction selected was forwards, selecting the forwards direction at this stage will send the sample to

waste and selecting the backwards direction will send the sample back to the sample container. Once the required direction has been selected press the key adjacent to the tick icon to save the calibration sequence and return to the operating menu. To exit the sipper calibration sequence without saving any changes press the back key at any point during the calibration sequence.




To perform a measurement place the sipper tubing into the sample and press the key below the sipper pump icon.




Confirmation will be needed to start the sipper pump. Press the key adjacent to the cross icon to cancel and return to the operating menu. Press the key adjacent to the tick icon to confirm and start the sipper pump. The pump will run for the previously recorded sample take up time. Ensure that the flow through cuvette contains enough sample before pressing the key below the measure sample icon.

Once the measurement has been performed remove the tubing from the sample and press the key below the sipper pump icon to perform the next stage of the calibration sequence.




Confirmation will be needed to start the sipper pump. Press the key adjacent to the cross icon to cancel and return to the operating menu. Press the key adjacent to the tick icon to confirm and start the sipper pump. The pump will run for the previously recorded air gap take up time.

If an air gap of zero was previously selected this screen will not appear and the calibration sequence will continue to sample disposal.




Once this stage of the calibration sequence is complete press the key below the sipper pump icon to dispose of the sample. Confirmation will be needed to start the sipper pump. Press the key adjacent to the cross icon to cancel and return to the operating menu. Press the key adjacent to the tick icon to confirm and start the sipper pump. Depending on the disposal route previously selected the sample will either go to drain or back to the sample container.

18.3.4 Combined sipper Peltier



When the combined sipper Peltier is in use the sipper Peltier icon is displayed in the bottom right hand corner of the screen. The current temperature is displayed above the set point temperature adjacent to the sipper Peltier icon. Adjacent to the Peltier icon is an arrow to indicate if the current temperature is below or above the set temperature. The pump direction is displayed by an arrow icon below the sipper Peltier icon. The combined sipper Peltier pump

combines the functionality of the Peltier and sipper pump. To open the sipper Peltier settings hold the key below the sipper Peltier icon for 2 seconds.



The settings menu is the same as the sipper pump settings except for the Peltier icon in the top left hand corner. Pressing the key adjacent to the Peltier icon will open the Peltier settings enabling the temperature to be set. Refer to section 18.3.2 for more details. The sipper pump can operate in a manual or timed mode. Refer to section 18.3.3 for more details.

18.4 SPARES

Part Code	Description of Spare Part
730 545	Xenon lamp module
630 304	10x10mm (70μl cuvette holder)
037 702	Paper roll for printer
021 060	24V 65W power supply unit with various plug attachments

SECTION 19 – Maintenance and service

19.1 ROUTINE MAINTENANCE

Ensure the external surfaces of the unit are clean and free from dust. The sample area should always be kept clean and any accidental spillage should be wiped away immediately. To give added protection when not in use, the unit should be disconnected from the mains supply and covered with the optional dust cover.

19.2 LAMP REPLACEMENT

19.2.1 Xenon Lamp Module Replacement

This must be done by an accredited service engineer. Refer to section 19.4 for more details.

19.3 FIRMWARE UPDATE PROCEDURE

The Genova Plus spectrophotometer allows users to update the instrument's firmware using a USB flash drive using the following procedure:

- 1. Download the latest version of the instrument's firmware from the Jenway website at www.jenway.com/Software.asp and copy the file to a USB flash drive.
- 2. With the instrument switched off, insert the USB flash drive into the USB memory stick slot of the instrument.
- 3. Switch on the power to the instrument.
- 4. The instrument will indicate that a firmware update file has been found and the progress of the update process will be indicated on the instrument's screen.
- 5. When the update is complete, the instrument will continue with its normal power on procedure.

19.4 SERVICE

Our dedicated service team are on hand to help in the unlikely event that your Jenway equipment develops a fault. Please contact them by one of the following means with a clear description of the problem:

E-mail: service@bibby-scientific.com

Tel: +44 (0) 1785 810475 Fax: +44 (0) 1785 810471

On occasion it may be necessary for your equipment to be sent back to our Service Department for repair. In this case please contact the Service Department for a reference number which you should include with your faulty equipment. Please also ensure you include a clear description of the fault and a completed copy of our Decontamination Certificate. This is available as a downloadable pdf file at www. jenway.com, or contact us and we will be happy to fax you a copy. Please clearly mark the package for the attention of the Service Department and post to the following address:

Bibby Scientific Ltd Beacon Road Stone Staffordshire ST15 0SA United Kingdom

All replacement parts are guaranteed for 1 year and where ever possible, returned equipment is turned around in 10 working days.

SECTION 20 – Troubleshooting

20.1 ERROR CODES

If an error code is displayed it will be accompanied by a spanner icon and a symbol to indicate if the error is a warning (caution icon) or fatal (stop icon). If the error is fatal contact your local distributor or Jenway service department (refer to section 19.4). If the error is a warning it may be possible to retry the test. In this case a back icon will also be displayed. The table below shows the error codes:

Error Code	Symbol	Issue
Err 1	The state of the s	System Parameters Failure
	Fatal	This error indicates that the essential system parameters are corrupt. The most likely causes of this error are: 1. Fram chip failure. Solution: Restart the unit, if the problem persists contact a service technician.
Err 2		Operating Parameters Failure
	Warning	This error is a warning that the method and other user parameters have been reset. The most likely causes of this error are: 1. The methods were reset by pressing the top left button during the power on tests performed when the instrument is turned on. 2. The parameters have been corrupted so the instrument has reset itself. Solution:

Err 3





Dark Calibration Error

This error indicates that the dark level is too high during calibration. In normal operation the lamp is switched off during an operator initiated calibration sequence to ensure that the detector output is below a threshold level. The calibration is aborted and Err 3 is displayed if the detector output is above the threshold level.

The most likely causes of this error are:

Press the key adjacent to the tick icon to action.

- 1. The sample chamber lid has been left open during the calibration sequence.
- 2. The sample chamber lid was opened during the calibration sequence.
- 3. There is a fault on the detector PCB.

Solution:

Ensure the sample chamber is closed completely. Press the key adjacent to the back icon to retry the dark calibration.

Err 4





Fatal

Microswitch Failure (service only)

This error indicates that the microswitch was not found.

The most likely causes of this error are:

1. The microswitch is broken.

Solution:

Contact a service technician.

Err 5





Warning

Light Saturation Not Found

This error indicates that the peak light hasn't been found at zero.

The most likely causes of this error are:

- 1. Lamp failure.
- 2. Deteriorating lamp signal.
- 3. Sample or cuvette in the sample holder.

Solution:

Ensure the sample holder is empty. Restart the unit, if the problem persists contact a service technician.

Err 7







USB Module Failure

This error indicates the instrument is unable to detect a response from the UBS module.

The most likely causes of this error are:

1. USB port failure.

Solution:

Press the key adjacent to the tick icon to carry on using the instrument. Restart the unit, if the problem persists contact a service technician.

Err 8





Warning



Redo

Unable to find Vane on Turret

This error indicates that the vane position zero on the turret cannot be found.

The most likely causes for this error are:

1. The turret carousel has been removed and not replaced. Solution:

Check if the turret is in the sample chamber and inserted properly. Press the key adjacent to the back icon to try rechecking.

20.2 TOUBLESHOOTING GUIDE

Issue	Solution
Unable to achieve zero absorbance or 100% transmittance when calibrating	Ensure that there is not a sample in the sample chamber. Ensure the instrument lid is closed before and during the calibration. Ensure the lamp is working – if the lamp has failed please request service assistance.
Unable to achieve a reading when measuring a sample	Ensure the correct cuvette is being used so that light isn't being absorbed by the cuvette. Ensure the sample isn't too dense that light is not transmitted through the sample. Ensure the lamp is working.
Unable to add additional points to the spectral points analysis table	The table can only hold 6 points. Delete one or more points before selecting additional points to add to the table.
Unable to print results using the internal printer	Ensure internal printer selected in autolog menu. Ensure there is paper in the unit. Ensure there is a result displayed on the screen.
Unable to save results to the USB memory stick	Ensure the USB stick is inserted into the front of the unit. Ensure the USB memory stick has free capacity. Ensure there is a result displayed on the screen.
Unable to continue kinetics measurement after cancelling abort action	Due to the nature of the kinetics measurements stopping the measurement before completion will result in some measurement time being lost. Therefore the experiment cannot be continued. It must be restarted.
The peaks and valleys table icon is not displayed following a spectrum scan	The peaks and valleys threshold is turned off. Change this value to 1%, 5% or 10% and the peaks and valleys table icon will be displayed.
The measure sample icon disappears after changing the wavelength	A calibration must be performed at the new wavelength. When the calibration is complete the measure sample icon will be displayed.
Unable to save methods	Ensure the method lock is not active. Ensure the method is not a pre-loaded locked method.

20.3 TECHNICAL SUPPORT

Jenway have a dedicated Technical Support team made up of experienced scientists who are on hand to help with any applications advice and questions you may have about our products and how to use them. If you require any technical or application assistance please contact the team at:

E-mail: jenwayhelp@bibby-scientific.com

Phone: +44 (0)1785 810433 Fax: +44 (0)1785 810405

Declaration of Conformity

UV/Visible Spectrophotometer, Genova Plus

This product complies with the requirements of the EU Directives listed below:

2004/108/EC

EMC Directive.

2006/95/EC

Low voltage Directive (LVD)

Compliance with the requirements of these Directives is claimed by meeting the following standards:

EN 61326-1:2006 (Electrical Equipment for Measurement, Control and Laboratory use).

EN 61010-1: 2010

(Safety Requirements Electrical Equipment for Measurement, Control and Laboratory use)

CE mark affixed 2012

Signed:

(Mr S. Marriott)

Date:

Authority: Technical Director

Bibby Scientific Ltd

Bibby Scientific Bibby Scientific Ltd - Stone - Staffs - ST15 OSA - UK Tel: +44 (0) 1785 812121 - Fax +44 (0) 1785 813748

SECTION 22 – Glossary of icons

Mode	ICON	Description
Common	5	Back key
Common	/	Tick icon - Done/yes
Common	X	Cross icon – Cancel/no
Common		Printer icon - Print/open printer settings
Common		No results to send to printer
Common		Computer icon - RS232 serial port for connection to an external serial printer or a computer
Common		No results to send to RS232
Common	English	English icon - Language selection
Common	\Diamond	USB memory stick
Common		Save to USB memory stick
Common		Load from USB memory stick
Common		Result already saved to USB memory stick
Common		Single method save icon
Common	1-16	1 – 16 (or 48) method save icon
Common	🗳 ¹ 🛗	Single method open icon
Common	1 -16 ☐	1 – 16 (or 48) method open icon
Common		Axis icon – View the result graphically
Common	ABC	ABC icon – View the results as a text file
Common	\(\frac{1}{2}\)	Arrow icon - Results page down, move left, decrease
Common	➾	Arrow icon - Results page up, move right, increase
Common	₽	Arrow icon – Move down, decrease
Common	Û	Arrow icon – Move up, increase
Common	[]0	Calibrate to zero icon
Common		Pencil icon - Select letter/number

Common	r\$	Eraser icon - Delete letter/number
Common	AB	AB icon - Change letter case/number
Common	<u> </u>	Delete
Common		Method icon – opens method selection screen
Common		Save method/result
Common	<u>-2</u>	Open method/result
Common		Units icon – opens unit selection screen
Common	⊜ 0.000	Resolution
Common	400nm	Wavelength
Common	ABS/%T	Abs/%T icon - Operating mode either absorbance or % transmittance
Common	Ţ	Caution icon – accompanied by error code
Common	1000	Check number
Common		Stop icon – accompanied by error code
Main Menu	100.000M 0.0000Ms xF	Opens concentration measurement mode
Main Menu		Opens kinetics measurement mode
Main Menu	0.000aks 100%T 470nm	Opens photometrics measurement mode
Main Menu	1.00PPM 1.000Abs	Opens quantitation measurement mode
Main Menu	200 500	Opens spectrum measurement mode
Main Menu	<u> </u>	Opens purity scan measurement mode
Main Menu	# <u>851</u> =1.7 #\$52 =1.7 \$\$\text{\$\exititt{\$\text{\$\exititt{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$\text{\$	Opens multi-wavelength measurement mode
Main Menu	PROTEIN	Opens protein measurement menu
Main Menu	DONA	Opens DNA measurement menu
Main Menu	0D 600	Opens OD600 measurement mode
Main Menu	×	Instrument settings

Main Menu	12.00	Time/date icon
Time & Date	(1)	Clock icon - Set time
Time & Date		Calendar icon - Set date
Time & Date		Toggle icon – Switches date format
Autolog	` Z	Autolog icon - Opens autolog menu
Autolog		Printer icon - Autolog to printer
Autolog		USB icon - Autolog to USB memory stick
Autolog		Computer icon - Autolog to computer or external serial printer through RS232 serial port
Autolog	× 0005	Sample icon - Number of sample measurement repetitions
Autolog	030s 🌄	Timer icon - Time interval between each sample measurement repetition
Autolog	₽₽	Batch ABC icon - Set batch name for repeated measurements
Autolog		Batch append – add existing results
Autolog	`	Batch delete – overwrite existing results
Instrument Settings	**	Closed padlock icon - Settings locked
Instrument Settings	❖	Open padlock icon – Settings unlocked
Instrument Settings	ð	Methods unlocked – method selection menu enabled
Instrument Settings	6	Methods locked – method selection menu disabled
Instrument Settings	123	Security code
Instrument Settings		Mode selection
Instrument Settings		Mode shown
Instrument Settings		Mode not shown
Instrument Settings		User ID
Instrument Settings	lacktriangle	Contrast
Photometrics	題	Measure sample
Photometrics	₹2	Toggle icon – switches between ABS/%T
Concentration	\times	Settings menu
Concentration	≣ _∗ F	Measure to a factor
Concentration		Measure to a standard
Concentration	0.000 ABS	Calibrate to zero absorbance
Concentration	0.000	Calibrate to a standard

Concentration	© 00	Calibrate to zero absorbance or standard
Concentration	хF	Factor menu
Concentration	₽	Standard menu
Concentration	001	Resets value to one
Concentration		Check standard
Spectrum	<u> </u>	Scan settings menu
Spectrum	₹	Hand icon – Manual y-axis scaling
Spectrum	※	Hand icon with cross through it - Auto y-axis scaling
Spectrum	2	Scan interval
Spectrum	<u></u>	Baseline scan
Spectrum	<u> </u>	Baseline scan in progress
Spectrum	$\overline{\sim}$	Scan sample
Spectrum	 ✓•	Sample scan in progress
Spectrum	~ ₹	Peaks and valleys threshold turned off
Spectrum	<u> </u>	Peaks and valleys above threshold 5% are shown
Spectrum	\triangle	Peaks and valleys table
Spectrum	\triangle	Show peaks only
Spectrum	\triangle	Show valleys only
Spectrum	4	Spectral points analysis
Spectrum	«	Double less than icon- decrease the wavelength by 10 times scan interval
Spectrum	<	Single less than icon - decrease the wavelength by 1 times scan interval
Spectrum	>>	Double greater than icon - increase the wavelength by 10 times scan interval
Spectrum	>	Single greater than icon - increase the wavelength by 1 times scan interval
Spectrum	λ	Wavelength icon - manually enter the wavelength
Spectrum	. \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Add points to the spectral points analysis table
Spectrum		View spectral points analysis table
Spectrum	$\overline{\triangle}$	Data point interval – used in print setup
Quantitation		Measure sample
Quantitation		Quantitation table – Opens quantitation table

Quantitation	& ⁶ 6	Number of standards
Quantitation	1/	View standard curve
Quantitation	,/x	Curve fit – enables the curve fit to be adjusted
Quantitation	Σ	Sigma icon – Displays curve statistics
Quantitation		Measure standards
Quantitation		Replicate measurement selection
Quantitation		Tick icon - Read Standard
Quantitation	5	Back icon – Re-measure previous standard
Quantitation	\times	Cross icon – Cancel creation of new standard curve
Quantitation	, /x	Curve statistics – used in print setup
Quantitation	<u>,</u>	Hand icon – Manual replicates
Quantitation	%	Hand icon with cross through it – Automatic replicates
Kinetics	×	Settings menu
Kinetics	₹	Hand icon – Manual y-axis scaling
Kinetics	%	Hand icon with cross through it - Auto y-axis scaling
Kinetics	0000s	Start time pause – Opens lag time/start on level menu
Kinetics	000	000 - Resets lag time, standard or factor values to zero
Kinetics	 	Clock icon - Set the lag time
Kinetics	∏AЬ\$ %T	ABS/%T icon - Set the start on level
Kinetics	>	Greater than - Start above
Kinetics	<	Less than - Start below
Kinetics	>	No start on level set
Kinetics	E ()	Start kinetics measurement
Kinetics Kinetics	_	Start kinetics measurement Kinetics measurement in progress
	<u></u>	
Kinetics	_	Kinetics measurement in progress
Kinetics Kinetics	<u></u>	Kinetics measurement in progress Sigma icon - Post measurement statistics
Kinetics Kinetics	∑ ∆ ∆ xF	Kinetics measurement in progress Sigma icon - Post measurement statistics Kinetics moving line
Kinetics Kinetics Kinetics Kinetics	<u>ν</u> Σ	Kinetics measurement in progress Sigma icon - Post measurement statistics Kinetics moving line Update factor in settings

Kinetics	>>	Double greater than icon - Increase the time by 5 seconds intervals
Kinetics	>	Single greater than icon - Increase the time by 1 second intervals
Kinetics	W	Data point interval – used in print settings
Multi-wavelength	$\overline{\mathbf{x}}$	Settings menu
Multi-wavelength	*F2 *F1Σ	Calculation factors menu
Multi-wavelength	_* г, – _× F 1	Calculation factor entry
Multi-wavelength	Σ=	Calculation equation selection
Multi-wavelength	$\overline{\lambda}^{_1}$	Update measurement wavelength
Multi-wavelength	λ^4	Select number of measurement wavelengths
Multi-wavelength	IJ	Dilution ratio – sample volume
Multi-wavelength		Dilution ratio – diluent volume
Multi-wavelength	Ш	Dilution ratio – calculated
OD600	$\ddot{\mathbf{x}}$	Settings menu
OD600	:cf(×)	Update instrument factor
OD600	\triangle	Update calibration standard
OD600	хF	Update factor in settings
OD600	U	Dilution ratio – sample volume
OD600	닖	Dilution ratio – diluent volume
OD600	L	Dilution ratio – calculated
Multi-wavelength plus	$\bar{\mathbb{X}}$	Settings menu
Multi-wavelength plus		Extended calculations screen
Multi-wavelength plus	${}_{*F_1}^{*F_2}\Sigma$	Calculation factors menu
Multi-wavelength plus	_× F 1	Calculation factor entry
Multi-wavelength plus	∑≡	Calculation equation selection
Multi-wavelength plus	λ^{1}	Update measurement wavelength
Multi-wavelength plus	$\lambda_{\!\scriptscriptstyle ullet}^{\!\scriptscriptstyle 4}$	Reference wavelength - active
Multi-wavelength plus	U	Dilution ratio – sample volume
Multi-wavelength plus		Dilution ratio – diluent volume
Multi-wavelength plus	Ш	Dilution ratio – calculated
	_	

Accessories		No single cell - Method created on a unit with a single cell accessory fitted
Accessories		8 cell turret icon - the automatic 8 cell turret is in use
Accessories		Error finding cell position 0 on turret
Accessories		No turret - Method created on a unit with a turret accessory fitted
Accessories	°C	Degrees Celsius
Accessories	°F	Degrees Fahrenheit
Accessories	120 Ø 135 Ø⊽	Peltier accessory in use – current temperature is below set point. The current temperature is displayed above set point temperature
Accessories		No Peltier - Method created on a unit with a Peltier accessory fitted
Accessories	♣ ;	Sipper pump in use – running in forward direction
Accessories	,	Sipper pump in use – running in reverse direction
Accessories	9	Timed sipper pump
Accessories	***	Timed sipper pump calibration sequence
Accessories	>	Start sipper pump – enables take up time to be set
Accessories	>>	Skip take up time – uses the previously set take up time
Accessories	000	000 – sets air gap to zero
Accessories		Stop sipper pump
Accessories	_	Reduce sample uptake/reduce air gap
Accessories	+	Increase sample uptake/increase air gap
Accessories		No sipper - Method created on a unit with a sipper accessory fitted
Accessories	*	Sipper Peltier pump in use
Accessories Peltier		No sipper Peltier - Method created on a unit with a sipper accessory fitted
Error	1	Spanner – refer to section 20



UK

Bibby Scientific Ltd. Beacon Road, Stone Staffordshire ST15 OSA United Kingdom Tel: +44 (0)1785 812121

Fax: +44 (0)1785 812121 Fax: +44 (0)1785 810405 e-mail: sales@bibby-scientific.com www.bibby-scientific.com

France

Bibby Scientific Limited Bâtiment Le Deltaparc Parc Silic PN2 7 rue du Canal BP 55437 VILLEPINTE 95944 ROISSY Charles de Gaulle France

Tel: +33(0)148 63 78 03 Fax: +33(0)148 63 78 01 e-mail: ventes@bibby-scientific.com www.bibby-scientific.com

North & South America

Bibby Scientific US Inc.
t/a Techne Inc.
3 Terri Lane, Suite 10
Burlington, NJ 08016 USA
Toll Free (in NA): 800-225-9243
Tel: +1 609 589 2560
Fax: +1 609-589-2571

e-mail: labproducts@techneusa.com www.techneusa.com

Italy

Bibby Scientific Italia Srl Via Alcide de Gasperi 56 20077 Riozzo di Cerro al Lambro Milano Italia Tel: +39 (0)2 98230679 Fax: +39 (0)2 98230211 e-mail: marketing@bibby-scientific.it www.bibby-scientific.it

Middle East

Bibby Scientific Middle East Ltd. PO Box 27842, Engomi 2433 Nicosia Cyprus Tel: +357 22 660 423

Fax: +357 22 660 424 e-mail: sales@bibby-scientificme.com

Asia

Bibby Scientific - Singapore Prudential Tower, Level 26 30 Cecil Street Singapore 049712 Tel: +65 6631 2976 Fax: +44 (0)1785 810405 e-mail: info@bibby-scientific.com www.bibby-scientific.com